

LICENSEE EVENT REPORT

NUCLEAR REGULATORY COMMISSION

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
 7 8 9 14 15 25 26 30 57 58
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
 0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 0 | 7 | 1 | 1 | 0 | 5 | 8 | 0 | 8 | 1 | 1 | 2 | 4 | 8 | 0 | 9
 7 8 60 61 68 69 74 75 80
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During the performance of SI 4.7.D.1-d (TS 3.7.D.1), it was found that the
 0 3 | internals for the excess flow check valve in instrument line to PDIS-75-28,-56;
 0 4 | PDT-85-17,-18, PI-85-19, and PDT-68-52 was missing. There was no effect on the
 0 5 | public health or safety. There are no redundant systems. Previous events: None.
 0 6 |
 0 7 |
 0 8 |

0 9 | I | B | 11 | A | 12 | E | 13 | V | A | L | V | E | X | 14 | C | 15 | G | 16 |
 7 8 9 10 11 12 13 18 19 20
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 17 | LER/RO REPORT NUMBER | 8 | 0 | 21 | 22 | 0 | 4 | 6 | 24 | 26 | 0 | 1 | 28 | 29 | T | 30 | 0 | 32 |
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
 C | 18 | G | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | Y | 23 | N | 24 | N | 25 | M | 0 | 9 | 0 | 26
 33 34 35 36 37 40 41 42 43 44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause was construction installation error. The 1/2 inch flow check valve
 1 1 | model 280619 was replaced and SI 4.7.D.1-d was successfully completed. A
 1 2 | mechanical maintenance instruction will be written with a QC sign off for
 1 3 | proper installation of valve parts.
 1 4 |

1 5 | H | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Surveillance testing. 32
 7 8 9 10 12 13 44 45 46
 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION


1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
 7 8 9 10 11 44 45
 ACTIVITY CONTENT RELEASSED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
 7 8 9 11 12 13
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | NA | 41
 7 8 9 11 12
 PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | NA | 43
 7 8 9 11 12
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | NA | 45
 7 8 9 10 11 12
 PUBLICITY ISSUED DESCRIPTION NRC USE ONLY



LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 8046 Technical Specification Involved 3.7.D.1

Reported Under Technical Specification 6.7.2:A.3

Date of Occurrence 11/05/80 Time of Occurrence 0900 Unit 2

Identification and Description of Occurrence:

During refueling while performing SI 4.7.D.1-d, it was found that the intervals for the excess flow check valve in instrument line to PDIS-75-28,-56; PDT-85-17,-18; PI-85-19; and PDT-68-52 were missing.

Conditions Prior to Occurrence:

Unit 1 @ 97%

Unit 2 @ refueling

Unit 3 @ 92%

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None.

Apparent Cause of Occurrence:

Construction installation error.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no danger to the health or safety of the public.

Corrective Action:

Valve was replaced. Mechanical maintenance instruction will be written.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

1. The first part of the document is a list of names and addresses.

2. The second part of the document is a list of names and addresses.