

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8010100337 DOC. DATE: 80/10/02 NOTARIZED: NO
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv
 AUTH. NAME AUTHOR AFFILIATION
 CURTIS, N.W. Pennsylvania Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 GRIER, B.H. Region 1, Philadelphia, Office of the Director

DOCKET #
 05000387
 05000388

SUBJECT: Supplemental deficiency rept re Anchor Darling Valve Yokes.
 Condition continues to be tracked under MCAR 1-59. Final rept
 will be forwarded by Jan 1981, after completion of
 manufacturer testing.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Send I&E 3 copies FSAR & all amends.
~~Send I&E 3 copies FSAR & all amends.~~

05000387
 05000388

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	A/D LICENSNG 04	1	YOUNGBLOOD, B 05	1
	RUSHBROOK, M. 06	1	STARK, R. 07	1
INTERNAL:	AD/RCI/IE 17	1	AEOD 18	1
	ASLBP/J. HARD	1	D/DIR HUM FACIS	1
	EDO & STAFF 19	1	EQUIP QUAL BR11	1
	HYD/GEO BR 22	1	I&E 09	2
	LIC QUAL BR 12	1	MPA 20	1
	NRC PDR 02	1	OELD 21	1
	PROC/TST REV 13	1	QA BR 14	1
	<u>REG FILE</u> 01	1	RUTHERFORD, W. IE	1
	STANDRDS DEV 21	1		
EXTERNAL:	ACRS 16	16	LPDR 03	1
	NSIC 08	1		

OCT 14 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR 40 ENCL 0

R

PP&L

TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101

PHONE: (215) 821-5151

NORMAN W. CURTIS
Vice President-Engineering & Construction-Nuclear
821-5381

October 2, 1980

50-387
50-388

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION
STATUS UPDATE OF DEFICIENCY ON
ANCHOR DARLING VALVE YOKES
ERS 100450/100508 FILE 840-4/900-10
PLA-551

Reference: PLA-511 dated July 21, 1980
PLA-505 dated July 7, 1980

Dear Mr. Grier:

This letter serves to supplement the above referenced correspondence which advised the Commission of the deficiency involving cracked valve yokes. The condition continues to be tracked under Bechtel's MCAR 1-59.

PP&L has been advised that the final report on the condition will be delayed pending completion of Anchor Darling's NDE testing of suspect valve yokes. Thus we expect to provide our final report under the provisions of 10CFR50.55(e) by January, 1981.

Very truly yours,

NW Curtis

N. W. Curtis
Vice President-Engineering & Construction-Nuclear

FLW:mcB

cc: Mr. Victor Stello (15)
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Robert M. Gallo
U. S. Nuclear Regulatory Commission
P.O. Box 52 Shickshinny, PA 18655
PENNSYLVANIA POWER & LIGHT COMPANY

B019
S1/0

8010100337

S