

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7907270258 DOC. DATE: 79/07/23 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania 05000387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylvania 05000388

AUTH. NAME: CURTIS, R.W.
 RECIP. NAME: GRIER, B.H.
 AUTHOR AFFILIATION: Pennsylvania Power & Light Co.
 RECIPIENT AFFILIATION: Region 1, Philadelphia, Office of the Director

SUBJECT: Updates until 790623 deficiency report, letter re unsatisfactory field welding & inspection of shear studs. Required shear stud repairs have been completed.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: L
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: SEND I+E = 3 cys FSAR + ALL AMOTS. LA - 1 CY EVERYTHING (ORNL)

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES		
		LTR	ENCL		LTR	ENCL	
ACTION:	14 PM MINER	1		15 BC LWR 3	1		
	20 LA LWR 3	1		21 ADVASSALLO	1		
INTERNAL:	01 REG. FILE	1		02 NRC PDR	1		
	05 I&E	2	2	07 EDO & STAFF	1		
	08 MPA	1		09 DEPY DIR DPM	1		
	10 QAB	1		11 STANDRDS DEV	1		
	12 JORDAN, E/IE	1		13 FIELD COOR/IE	1		
	16 AD FOR ENGR	1		17 AD PLANT SYS	1		
	17 AD REAC SFTY	1		19 AD SYS/PROJ	1		
	22 DIR DPM	1		23 OELD	1		
	AD/SITE TECH	1		DIRECTOR DSE	1		
	GEOSCIENCES BR	1		STRUCT ANLYS BR	1		
	EXTERNAL:	03 LPDR	1		04 NSIC	1	
		24 ACRS	16	10			

JUL 30 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 44 ENCL 6

MA 1
 61

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

July 23, 1979

REGULATORY DOCKET FILE COPY

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 17406

SUSQUEHANNA STEAM ELECTRIC STATION
REPORTABLE DEFICIENCY REGARDING UNSATISFACTORY FIELD
WELDING AND INSPECTION OF SHEAR STUDS
ERs 100450/100508 FILE 840-4
PLA-385

Dear Mr. Grier:

This letter is in reference to PP&L's letter PLA-265, dated June 23, 1978, which transmitted a Definitive Report on the subject deficiency at Susquehanna Steam Electric Station. The required shear stud repairs as described in the Definitive Report have been completed.

Please advise should you require further information.

Very truly yours,



N. W. Curtis
Vice President-Engineering & Construction

JDV:mcb

cc: Mr. Victor Stello (15)
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director (1)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. R. M. Gallo, Reactor Inspector (1)
Reactor Construction and Engineering Support Branch
U. S. Nuclear Regulatory Commission
Region I 631 Park Avenue
King of Prussia, PA 19406

3019
5/10