

# LICENSEE EVENT REPORT

CONTROL BLOCK:                                         (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 NYNMPL 200-0000000-00 341111 4 5

CON'T  
0 1 REPORT SOURCE I 605000220 70207811 8 0309811 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation while performing a monthly Fire System Preventative Maintenance

0 3 Test it was found that the Electric Fire Pump failed to start. This had no significant

0 4 safety concerns since the alternate Fire Pump was available and the item was readily

0 5 corrected with the Pump being returned to service in approximately two hours.

0 6 \_\_\_\_\_

0 7 \_\_\_\_\_

0 8 \_\_\_\_\_

0 9 SYSTEM CODE AB 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE CKTBRK 14 COMP. SUBCODE A 15 VALVE SUBCODE Z 16

(17) LER/RO REPORT NUMBER 81 2122 SEQUENTIAL REPORT NO. 006 2426 OCCURRENCE CODE 03 2829 REPORT TYPE L 30 REVISION NO. 0 32

ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 3740 ATTACHMENT SUBMITTED N 23 NFRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER G080 4447

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The inability to start was found due to a broken prop spring in the 4160V motor

1 1 breaker. This item was readily replaced which resulted in satisfactory pump

1 2 initiation and operability.

1 3 \_\_\_\_\_

1 4 \_\_\_\_\_

FACILITY STATUS E 28 % POWER 087 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION OPERATOR OBSERVATION 32

ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

2 0 N 44 45 NAME OF PREPARER P. Harrison

NRC USE ONLY  
 68 69 80  
 (315) 343-2110, ext. 1212  
 PHONE: \_\_\_\_\_

