

ATTACHMENT TO LER 80-08, Rev.1
CONSUMERS POWER COMPANY
PALISADES PLANT
DOCKET 50-255

Discussion. Containment local leak rate testing is performed in accordance with Palisades Technical Specifications and 10CFR50 Appendix J in order to determine the magnitude of leakage through containment penetrations. Acceptance criteria established by 10CFR50 Appendix J permit detection of degradation in penetration boundaries (eg, gaskets, seals, valve seats, valve packings) prior to leakage rates reaching the allowable containment leak rate.

During the current refueling outage a program to systematically review all Technical Specification surveillance tests was undertaken to assure, among other items, adequacy of test methods and compliance with requirements of basis documents. Review of the local leak rate test program revealed a number of deficiencies which were not apparent when the program was first established. Among these deficiencies were failure to test all penetrations and failure, in some cases, to apply the containment design pressure (55 psig) across the penetration boundary (for example, in the case of the condensate makeup to the shield cooling system, the system pressure exceeded the test pressure -- in previous tests, the test procedure (RO-32) did not require compensating for this pressure difference). The procedure, which has been extensively revised now includes all testable penetrations and requires 55 psid to be applied across containment penetration boundaries.


Test Results. Results of leakage measurement prior to and following maintenance are tabulated in Table 1. In summary, the "as found" leakage was determined to be 442,260 cc/min; the post maintenance leakage was 29,429 cc/min. The Technical Specification limit for local leak testing is 65,200 cc/min.

Evaluation. Although the basic cause of the leakage was primarily deterioration of valve internals, the inadequacies in the previous version of test procedure RO-32 prevented timely detection of valve deterioration. Accordingly, the abnormally high leak rate detected during this outage would not be expected during the next test. It should be noted that because most local leak tests are performed by pressurizing between two valves in series, the measured leakage is in fact the sum of the individual leakage of the two valves. Therefore, the actual leakage could be expected, in most cases, to be considerably less than this measured leakage.


Refer to Figure 1 for the following discussion. Regarding penetration 28 (containment air sample) the design of the handswitch which operates the solenoid valves is such that one of the solenoid valves (2402-L,M,N, or P) is always energized (open). As a result, a single valve boundary existed between containment atmosphere and the containment hydrogen vent line.

This penetration has been modified by the addition of two manual valves which provide containment isolation. Additionally, valve SV-2402-L was previously oriented such that it provided an essentially leak-tight boundary for flow from the hydrogen exhaust line but not in the reverse direction. The valve orientation has been reversed such that leakage through the valve should not occur during containment sampling operations.

Corrective Action. Corrective action to reduce leakage has consisted of valve repair, valve replacement, packing adjustment, valve reorientation, and in the case of penetrations which are no longer used, installation of blank flanges to "eliminate" those penetrations.



AS BUILT



AFTER MODIFICATION

FIGURE 1

NOTE: This drawing depicts the containment isolation boundary for penetration 28, but does not include all valves and components.

PENETRATION DESCRIPTION	AS FOUND LEAKAGE (cc/min)	AFTER MAINTENANCE LEAKAGE (cc/min)
Purge Air Supply	2,740.2	5.3
Purge Air Exhaust	3,354.7	11.0
Purge Exhaust Bypass	12.9	201.6
Service Air	0.9	-
Cond to Shld Clg Surge Tank	151,393.	29.7
CCW In	51,301	0
CCW Out	36.5	-
Cont. HP Switch	-	0
CWRT Vent	37.5	-
N ₂ to Quench Tank	186.4	-
ILRT Fill Line	74.0	-
Cont. Air Sample Line	52,233	0
Safety Injection Tank Drain	132,000.	195.7
Letdown to Purification I Ex	57.1	-
Primary Syst Drain Pump Disch	2,296.	-
Cont Building Htg Stm Return	22,151	2,414
Cont Building Htg Stm Supply	368.1	-
Pressurizer Deadweight Tester	48.0	0
Sample Tube From Decay Coils	221.5	-
Degasifier Pump Disch	2,081.4	-
Demin Water To Quench Tank	165.	-
PCS Bleed Off	-	0
Containment Vent Header	4.1	-
Primary System Drain	81.8	-
Cont. HP Switch	-	0
CWRT Circulation Line	190	-
Containment Sump Drain	2,452	-
Reactor Cavity Fill and Recycle	2,545.8	-
ILRT Instrument Line	404.6	-
CWRT Pump Discharge	0	57.4
Air Supply to Air Room	927.6	-
CWRT	3.3	-
Reactor Cavity Drain and Recycle	570	-
Escape Lock (From SO-4)	1,850.2	-
Personnel Lock (From SO-4)	3,871.3	-
Equipment Hatch	4.4	-
North Elec. Pen	-	3,153.6
South Elec. Pen	-	804.9

PENETRATION DESCRIPTION	AS FOUND LEAKAGE (cc/min)	AFTER MAINTENANCE LEAKAGE (cc/min)
Transfer Winch Cable	649.9	201.0
"A" SG Sec Manway - N	2.4	-
"A" SG Sec Manway - S	488.4	-
"B" SG Sec Manway - N	2,358.8	-
"B" SG Sec Manway - S	1,122.5	-
TOTALS	"AS FOUND" 442,260	AFTER MAINTENANCE 29,492