

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • (517) 788-0550

May 21, 1981



Mr James G Keppler Office of Inspection and Enforcement Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 50-255 - DPR-20 - PALISADES PLANT - LICENSEE EVENT REPORT 81-016 -PIP DATALOGGER FAILURE

On the reverse side is LER 81-016 which is reportable under Technical Specifications 6.9.1.b.2.

Brian D Johnson

Burn 6

Senior Licensing Engineer

CC Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement NRC Resident Inspector-Palisades Plant

> 1/1 1/1

NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 1 (PLEASE PRINT O	R TYPE ALL REQUIRED INFORMATION)
0 1 M I P A L 1 2 0 0 - 0 0 0 0 - 0 0 7 8 LICENSEE CODE 14 15 LICENSE NUMBER 2	3 4 1 1 1 1 1 6 5 5 CAT 58
CON'T  O 1  SOURCE L 6 0 5 0 0 0 2 5 5 7 0 4 2 1  FEVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  O 2 During normal power operation, both the primar	
[0]3   failed. Condition is degraded mode of operation	
o 4   reportable per TS 6.9.2.b2.	
0 5   Primary datalogger was restored in approximate	ly 1.3 hours. No threat to
0 6   public health or safety existed. Refer to LER	
071	
0 8 1	
SYSTEM CAUSE CAUSE COMPONENT CODE  O 9  T D 10  E 12  A 13  I N S T R C	18 19 20
LER/RO EVENT YEAR REPORT NO. CO	DE TYPE NO.  3 L O O O O O O O O O O O O O O O O O O
Primary datalogger failed due to faulty circu	it board, which was replaced.
Secondary datalogger failure was caused by fa	ilure of typer. Replacement
of plant datalogging system equipment is bein	g evaluated.
1 3	
114	
	DISCOVERY DESCRIPTION (32)  Operator Observation
	LOCATION OF RELEASE 36
7 8 9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  1 7 8 9 11 12 13 N/A	80
PERSONNEL INJURIES NUMBER DESCRIPTION 41  1 8 0 0 0 0 40 N/A	80
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION  1 9 Z 42 N/A	
7 8 9 10 PUBLICITY	NRC USE ONLY
2 0 N/A 7 8 9 10	68 69 80
8106020 <i>313</i>	