

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

August 28, 1981

Mr. David P. Hoffman Nuclear Licensing Administrator
Consumers Power Company
1945 W. Parnall Road
Jackson, Michigan 49201

Dear Mr. Hoffman:

G RECEIVED 2

SEP 0-1.1981 3

West Microsoft School 1981 3

White Microsoft School 1981 3

Wh

The distribute an arrangement complex (1994).

By letter dated February 25, 1980 we informed all licensee/users of Westinghouse low-pressure turbines that stress corrosion cracks were being found in the keyway and bore areas of low-pressure discs. Because these cracks were considered to increase the probability of disc failure we requested that you perform ultrasonic inspections on your low-pressure discs and justify that your plant could continue to operate safely.

All Westinghouse low-pressure turbines at operating nuclear power plants have now been inspected, at least once, for keyway and bore cracks. Indication of one or both types of these cracks has been found at 20 plants. Although all factors related to cracking have not been positively established, operating experience indicates that crack initiation and growth are related to disc temperature and material characteristics. Westinghouse is continuing to evaluate the effect of other manufacturing and operational variables.

Until a satisfactory solution can be found we believe that it would be prudent for you to continue inspecting your low-pressure turbine discs on a schedule designed to minimize the probability that a crack will form and grow to a depth that would cause a disc to rupture. Westinghouse has developed a method to determine safe inspection and re-inspection frequencies and has submitted this information in Memorandum MSTG-1-P, June 1981 (Proprietary) for review by the NRC staff.

Our appraisal of the Westinghouse approach is presented in the enclosed Safety Evaluation. We conclude that inspection schedules based on the recommendations in the Westinghouse Memorandum will provide an acceptably high degree of assurance that discs will be inspected before cracks can grow to a size that could cause disc failure at speeds up to design speed. In our Safety Evaluation we list four criteria for an acceptable inspection schedule. It request that you commit to use these criteria for future disc

TAC 12586

inspections. We believe that such a commitment will reduce the probability for a safety problem to such a degree that the NRC staff would no longer need to monitor your turbine inspections except through the normal activities of our Office of Inspection and Enforcement. Your commitment would also eliminate the need for you to report these inspection results to the staff or to transmit the computerized disc data sheets that are prepared by Westinghouse.

Your response to this request should be submitted within 30 days of receipt of this letter.

I also take this opportunity to advise you that on June 11, 1981 Westing-house transmitted two proprietary reports related to turbine missiles for NRC staff review and evaluation. We have been advised by Westinghouse that the methodology described in these reports was used to provide its customers with estimates of the probability of disc rupture from stress corrosion cracking and with analyses of potential missile energies. We shall provide Westinghouse with our evaluation of this methodology as soon as our resources permit.

Sincerely,

Original signed by

Dennis M. Crutchfield, Chief Operating Reactors Branch #5 Division of Licensing

Enclosure: Safety Evaluation

cc w/enclosure See next page DISTRIBUTION

Docket

NRC PDR

Local PDR

NSIC

TERA

ORB REading

DCrutchfield

HSmith

TWambach

ACRS (10)

OELD

01&E (3)

SEPB

WRoss

					·
OFFICE	DI · ORR #5	ni . Const			
SURNAME	TWambachico	DCrutchfield		 	
}	V, ",	Unt 4		 	
DATE	8./28./8t		• • • • • • • • • • • • • • • • • • • •	 	 ··········

M. I. Millier, Esquires and appropriate U.S. Environmental Protection Isham, Lincoln & Beale Suite 4200 One First National Plaza Chicago, Illinois 60670

Mr. Paul A. Perry, Secretary Consumers Power Company 212 West Michigan Avenue Jackson, Michigan 49201 elza-esidentelalarian anasala artik

Judd L. Bacon, Esquire Consumers Power Company 212 West Michigan Avenue Jackson, Michigan 49201

Myron M. Cherry Esquire Suite 4501 One IBM Plaza Chicago, Illinois 60611

Ms. Mary P. Sinclair Great Lakes Energy Alliance 5711 Summerset Drive Midland, Michigan 48640

Kalamazoo Public Library 315 South Rose Street Kalamazoo, Michigan 49006

Agency Federal Activities Branch Region V Office ATTN: Regional Radiation Representative 230 South Dearborn Street Chicago, Illinois 60604

Charles Bechhoefer, Esq., Chairman Atomic Safety and Licensing Board exPanel day was some of the first the U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Dr. George C. Anderson Department of Oceanography University of Washington Seattle, Washington 98195 ब्रोति विवेशतान्त्रियात्वरत्तिः विविधित्तात्त्रात्वर्तिः विवादाः

Dr. M. Stanley Livingston 1005 Calle Largo Santa Fe, New Mexico 87501 Resident Inspector c/o U. S. NRC Palisades Plant Route 2, P. 0. Box 155 Covert, Michigan 49043

Township Supervisor Covert Township Route 1, Box 10 % William Action to Grand Was the Man was seen the contract Van Buren County, Michigan 49043

Office of the Governor (2) Room 1 2 Capitol Building Language Town The Control of the Control

Lansing, Michigan 48913

William J. Scanlon, Esquire 2034 Pauline Boulevard Williams Continue State S Ann Arbor, Michigan 48103 16.41.19.43

Palisades Plant ATTN: Mr. Robert Montross

Plant Manager Covert, Michigan 49043