	(7·77) ⁻	LICENSEE EVENT REPORT
B.		CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
	0 1	NJ S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 0 5 5 CAT 58
	0 1 8	REPORT L 6 0 5 0 0 0 2 7 2 7 0 1 1 0 2 7 9 8 0 1 1 8 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During normal operations, No. 12 Containment Fan Coil Unit (CFCU) was
	0 3	shifted to slow speed. The control operator noticed no indication of
	0 4	service water flow. The CFCU was declared inoperable and the action
	0 5	statement for T/S 3.6.2.3 was implemented. The CFCU was repaired and
,	0 6	returned to service within 23 hours. All other CFCU's were operable
	0 7	during this time. This is the second occurrence of this type. (78-85)
,	0 8	
	7 8	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE SUBCODE S C 11 E 12 A 13 V A L V O P 14 E 15 Z 16
	7 8	9 10 11 12 13 18 19 20 SEQUENTIAL OCCURRENCE REPORT TYPE NC. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32
		ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER ATTACHMENT NPRD-4 PRIME COMP. SUBMITTED FORM SUB. SUPPLIER MANUFACTURER ATTACHMENT NPRD-4 PRIME COMP. SUBMITTED FORM SUB. SUPPLIER MANUFACTURER ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. SUBMITTED FORM SUB. SUPPLIER NAMED ATTACHMENT NPRD-4 PRIME COMP. SUBMITTED FORM SUB. SUPPLIER NAMED ATTACHMENT NPRD-4 PRIME COMP. SUBMITTED FORM SUB. SUPPLIER NAMED ATTACHMENT NAMED AT
	1 0	The cause was a burned out coil in solenoid valve SV-624 which supplies
.•	111	control air for 12SW223, the service water flow control valve for
	1 2	No. 12 CFCU. The burned out coil was replaced and SP(0)4.6.2.3A was
	1 3	performed to confirm operability.
	14	
1		PACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 0 9 9 29 N/A a 31 Operator Observation
		9 10 12 13 44 45 46 80 CTIVITY CONTENT LOCATION OF RELEASE 36
	1 6 7 8	Z (33) Z (34) N/A
	1 7 7 8	NUMBER TYPE DESCRIPTION (39) 0 0 0 37 Z 38 N/A
	1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 N/A
	1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
	7 8	9 10 PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY
	20	Z (44) N/A
	7	901240136 A. W. Kapple PHONE: (609)365-7000 Salem Ext.