



Public Service Electric and Gas Company P.O. Box 168 Hancocks Bridge, New Jersey 08038

Salem Nuclear Generating Station

July 10, 1979

Mr. Boyce H. Grier
Director of USNRC
Office of Inspection and Enforcement
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

REGULATORY DOCKET FILE COPY

Dear Sir:

REPORTABLE OCCURRENCE 79-49/01P
SALEM NO. 1 UNIT LER

This letter will serve to confirm our verbal report to Mr. Leif Norrholm, the Salem NRC Resident Inspector, on July 10, 1979, advising of a reportable occurrence in accordance with Technical Specification 6.9.1.8.i.

Field installation inspection of concrete anchors used in pipe supports, other than those associated with I.E. Bulletin 79-02 and 79-02A, has revealed some deficiencies relating to improper anchor embedment. Corrective actions to identify and eliminate these deficiencies are in progress.

A detailed report will be submitted in the time period specified by the Technical Specifications.

Very truly yours,

H. J. Midura
Manager - Salem Generating Station

AWK:lds

CC: General Manager - Electric Production
Manager - Quality Assurance

A002
S 1/0

7908010 336