

APPENDIX A

NOTICE OF VIOLATION

Public Service Electric
and Gas Company

Docket No. 50-272

Based on the results of an NRC inspection conducted on April 27 - May 2 and May 22-23, 1979, it appears that one of your activities was not conducted in full compliance with conditions of your NRC Facility License No. DPR-70, as indicated below. This item is a deficiency.

Technical Specification 6.8.1, states in part, "Written procedures shall be established, implemented and maintained....." Administrative procedure No. 24, Rev. 5, paragraph 6.9.3 states: "Instruments for body scans or frisking shall be at various locations within the plant. Personnel shall monitor themselves whenever leaving a contaminated area, and the Controlled Access Area." Paragraph 6.9.4 states: "Individuals shall not wear Controlled Access Area protective clothing in a Clean Area."

Contrary to the above, on April 30, 1979, contamination control practices appeared not to be followed when a vendor representative failed to use the frisker to monitor himself on exiting the contamination control boundary at the containment air lock. On May 1, 1979, the same vendor again failed to use the frisker to monitor himself and in addition a member of the security force walked across the same stepoff pad from the contaminated side to the clean side without frisking or removing his protective clothing shoe covers.

7910010600