	CICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 0 9 2 6 7 9 8 1 0 0 9 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During shutdown operation, a break in the Hope Creek site fire main caused
0 2	During shutdown operation, a break in the hope treek site life main caused
0 3	the level in the Salem FWST's to drop below the T/S requirement. The X connect
0 4	valve 1FP30 was shut and Action Statement for T/S 3.10.1.b was implemented in
0 5	approximately one hour, the FWST level was returned to greater than 300,000 gals.
0 6	in each tank and the Action Statement was terminated. This is the second
0 7	occurrence of this type (79-27).
0 8	9 30
0 9 8	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE A B 10
	17 REPORT NUMBER 7 9 1 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 L 25 X 9 9 9 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0	The cause was lack of administrative control over the fire main X connect valve.
11	The valve was found open but was not authorized open by the Shift Supervisor.
1 2	Control had been established over the reach rod which operates the valve. A
1 3	locking device has been welded to the valve access tube to lock the cover in place.
1 4 7 8	9 - 80
1 5	9 FACILITY STATUS % POWER OTHER STATUS OTH
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 N/A LOCATION OF RELEASE 36 N/A N/A S0
1 7 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) O O O O O O O O O O O O O O O O O O O
1 8	NUMBER DESCRIPTION 41) 9 11 12 80
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
2 0	PUBLICITY ISSUED DESCRIPTION 45 N/A 7910160 40 NRC USE ONLY
7 8	9 10 68 69 20 NAME OF PREPARER A. W. Kapple PHONE: (609) 365-7000 Salem Ext. 628