LICENSEE EVENT REPORT

4	
•	

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)	
0 1	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 5 CAT 58	
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 1 1 0 5 7 9 8 1 2 0 3 7 9 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80	
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During cold shutdown operation, the meteorological instruments were out of service.	
0 3	Investigation showed the power supply inverter had failed. Maintenance Department	
0 4	was notified and T/S 3.3.3.4 Action Statement was implemented. The instruments	
0 5	were out for 74 hours before power was restored and the Action Statement was	
0 6	terminated. The plant was maintained in steady state cold shutdown conditions with	
0 7	no atmospheric radioactive releases. This is the third occurrence of this type.	
0 8		
09	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC	
1 0	LER'RO EVENT YEAR REPORT NO. 17 REPORT OF 17 9	
11	associated components of the inverter, including the normal emergency power	
1 2	switching circuit. Normal power was restored and the inverter will be replaced	
1 3	when a new inverter is available. Circuit tests verified instrument operability.	
1 4	9 80	
1 5	FACILITY STATUS STATU	
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34)	
17	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 11 12 13 13 N/A	
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 N/A	
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A	
7 8	9 PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY 10 NRC USE ONLY 10 NRC USE ONLY 10 NRC USE ONLY 10 N/A 10 N/	
NAME OF PREPARER A. W. Kapple PHONE: (609) 365-7000 Salem Ext. 628		