

LICENSEE EVENT REPORT

CONTROL BLOCK:

										1
--	--	--	--	--	--	--	--	--	--	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	1	2	0	0	-	0	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	--	---

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0	1	R	L	6	0	5	0	0	0	2	7	2	7	0	2	0	6	8	0	8	0	3	0	3	8	0	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

7 8 9 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | When performing a load test on the manipulator crane prior to fuel movement on
0 3 | April 25, 1979, a test of 3220 pounds was performed instead of 3250 as required
0 4 | by Technical Specification 4.9.6.1. In reviewing the procedure used for
0 5 | revision, it was determined the procedure's limit did not comply with Tech. Specs.
0 6 | The refueling operation was completed without incident involving the manipulator
0 7 | crane. (76-03, 78-21, 78-81)
0 8 |

0 9 |

			F	D	11							P	E	N	E	T	R	14				B	15				Z	16
--	--	--	---	---	----	--	--	--	--	--	--	---	---	---	---	---	---	----	--	--	--	---	----	--	--	--	---	----

7 8 9 SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP. SUBCODE 19 VALVE SUBCODE 20

17 | LER NO REPORT NUMBER 21 | 8 22 | EVENT YEAR 23 | 24 | SEQUENTIAL REPORT NO. 25 | 0 1 0 26 | OCCURRENCE CODE 27 | 28 | 0 3 29 | REPORT TYPE 30 | L 31 | 32 | REVISION NO. 33 | 34 | G 35 | Z 36 | Z 37 | 0 0 0 0 38 | HOURS 39 | Y 40 | ATTACHMENT SUBMITTED 41 | N 42 | NPRD-4 FORM SUB. 43 | N 44 | PRIME COMP. SUPPLIER 45 | S 3 9 2 46 | COMPONENT MANUFACTURER 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The procedure used for load testing did not correctly specify the load test
1 1 | requirements. The procedure required a test to a load of 3250 + 0 - 50 pounds,
1 2 | instead of at least 3250 pounds. The procedure will be revised prior to any
1 3 | future load tests.
1 4 |

1 5 |

				H	28	0	0	0	29	N/A	30	D	31	Procedure Review	32
--	--	--	--	---	----	---	---	---	----	-----	----	---	----	------------------	----

7 8 9 FACILITY STATUS 10 % POWER 12 OTHER STATUS 30 METHOD OF DISCOVERY 45 DISCOVERY DESCRIPTION 46

1 6 |

			Z	33	Z	34	N/A	35	N/A	36
--	--	--	---	----	---	----	-----	----	-----	----

7 8 9 ACTIVITY RELEASED 10 CONTENT OF RELEASE 12 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

1 7 |

				0	0	0	37	Z	38	N/A	39
--	--	--	--	---	---	---	----	---	----	-----	----

7 8 9 PERSONNEL EXPOSURES NUMBER 10 TYPE 11 DESCRIPTION 39

1 8 |

				0	0	0	40	N/A	41
--	--	--	--	---	---	---	----	-----	----

7 8 9 PERSONNEL INJURIES NUMBER 10 DESCRIPTION 41

1 9 |

				Z	42	N/A	43
--	--	--	--	---	----	-----	----

7 8 9 LOSS OF OR DAMAGE TO FACILITY TYPE 10 DESCRIPTION 43

2 0 |

				N	44	N/A	45
--	--	--	--	---	----	-----	----

7 8 9 PUBLICITY ISSUED 10 DESCRIPTION 45

8003060603 NRC USE ONLY

NAME OF PREPARER M. J. Murphy

PHONE: 609-935-0998

GPO 917-926