LICENSEE EVENT REPORT

	• • • • • • • • • • • • • • • • • • • •
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 6 TYPE 30 5 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 1 1 7 0 5 2 2 8 0 8 0 6 1 8 8 0 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	When the operating license was received, fire barriers were open due to the recent
0 3	removal of electrical cables, pipes and welding cables. The Technical Specification
0 4	3.7.11 requires the barriers to be sealed at all times.
0 5	
0 6	
0 7	
0 8	
	9 SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE CODE CODE SUBCODE COMPONENT CODE SUBCODE
0 9	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
	LER RO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32
	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER B 18 Z 19 Z 20 Z 21 0 0 0 0 0 Y 23 N 24 L 25 Z 9 9 9 9 2 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0	At the completion of construction, cables were removed from barriers and not sealed
11	immediately. In preparation for and prior to fuel load, all barriers were inspected,
1 2	verified sealed or sealed prior to core load.
1 3	
1 4	
1 5	9 F-ACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 28 0 0 0 0 29 N/A Z 31 Review of Surveillance Requirements
Α.	9 CTIVITY CONTENT 12 13 44 45 46 ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) [Z] (33) Z (34) N/A N/A N/A
7 8	9 10 11 44 45 80 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7	0 0 0 3 Z 3 N/A
1 8	NUMBER DESCRIPTION (41) 0 0 0 (40) N/A
	9 11 12 80 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION
1 9	Z 42 N/A
_	PUBLICITY AS ONLY NRC USE ONLY
	9 10 68 69 80 5
	NAME OF PREPARER M. J. Murphy PHONE: 609-935-0998