LICENSEE EVENT REPORT



CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)	
0 1 N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 6 57 CAT 58	
CON'T 0 1	
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0 2 While performing routing shift rounds at 1908 hours on April 22, 1981, an operator	ل
discovered a Service Water Leak emanating from the No. 13 Containment Fan Cooling	ر
Unit. In accordance with NRC IE Bulletin 80-24, the NRC was notified by telephone	1
at 2313 hours, with written confirmation transmitted within the next 24 hours.	- 1
Previous similar occurrences: 81-11 and 81-31.	ر ل
0 7	ل
, , , , , , , , , , , , , , , , , , , ,	 80
CODE SUBCODE SUBCODE SUBCODE W A 11 E 12 C 13 P I P E X X 14 A 15 Z 16 7 8	
LER RO EVENT YEAR SEQUENTIAL REPORT NO. CODE TYPE REVISION NC.	
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT TAKEN ACTION ON PLANT METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	0] 26 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) A leak was discovered in the weld connecting a carbon steel nipple to a stainless	ı
steel flange in the unit's outlet drain line. The weld was reworked requiring	_
the nipple to be replaced in kind.	_
1 3	١
7 8 9	 B0
FACILITY % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 G 28 0 0 0 29 N/A A 31 Operator Observation	
7 8 9 10 12 13 44 45 46 RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36	30
1 6 Z (33) Z (34) N/A N/A	30
1 7 0 0 0 37 Z 38 N/A	ل
7 8 9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION 41	
1 0 0 0 40 N/A 8 9 11 12 8	30
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A 7 B 9 10]
PUBLICITY ISSUED DESCRIPTION 45	30 20
2 0 N/A	17.92
10518 0275 W. J. Steele PHONE 609-935-0998	0