


Frederick W. Schneider
Vice President
Production

Public Service Electric and Gas Company 80 Park Plaza Newark, N.J. 07101 201/430-7373

September 22, 1981

Director Nuclear Reactor Division
Nuclear Regulatory Commission
Washington, D.C. 20555

Attention: Mr. Steven A. Varga
Chief, Operating Reactors
Branch No. 1
Division of Licensing



Gentlemen:

TURBINE DISC INSPECTIONS
NO. 1 AND 2 UNITS
SALEM NUCLEAR GENERATING STATION
DOCKET NOS. 50-272 AND 50-311

With reference to your August 21, 1981 letter, we have reviewed the four criteria for an acceptable Turbine Disc Inspection Schedule listed in the Safety Evaluation report attached to the letter.

We hereby commit to use the four criteria for scheduling future disc inspections at Salem Units 1 and 2.

The Westinghouse letter of September 14, 1981 confirms that the initial inspection of the Salem Unit No. 2 Rotor Discs can take place in five years; however, in conformance with license condition 2.C(17), "Turbine Inspection", of Facility Operating License No. DPR-75 for Salem No. 2 Unit, we will inspect the rotor discs at or before the second refueling.

Sincerely,

A handwritten signature in cursive script, appearing to read "F. W. Schneider".

*Boz
5/10*

8109290345 810922
PDR ADOCK 05000272
Q PDR