

Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038

Nuclear Department

January 4, 1985

U. S. Nuclear Regulatory Commission Office of Nuclear Reactor Regulation Division of Licensing Washington, DC 20555

Attention: Mr. Steven A. Varga, Chief Operating Reactors Branch, No. 1

TECHNICAL SPECIFICATION 4.4.6.5a INSERVICE INSPECTION OF STEAM GENERATOR TUBES SALEM GENERATING STATION UNIT NO. 2 DOCKET NO. 50-311

In accordance with the requirements of Technical Specification 4.4.6.5.a, we are providing the following information regarding Steam Generator tubes that were plugged during the second refueling outage on Salem Unit No. 2.

Steam Generator	Tube Plugged
No. 24	Row 44, Column 33
No. 23	Row 25, Column 10
No. 21 through 24	Row l, Columns l through 5 and
	Columns 90 through 94

8501100134 850104 PDR ADOCK 05000311

The Energy People

Mr. Steven A. Varga

Should you have any further questions, we would be pleased to discuss them with you.

Sincerely, E. A. Liden for

Manager - Nuclear Licensing and Regulation

C Mr. Donald C. Fischer Licensing Project Manager

> Mr. James Linville Senior Resident Inspector