

Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038-0236

Nuclear Business Unit

AUG 2 0 1997

LR-N970551 LCR S97-19

United States Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

CLARIFICATION FOR EXIGENT REQUEST FOR CHANGE TO TECHNICAL SPECIFICATIONS MOVABLE CONTROL ASSEMBLIES AND POSITION INDICATION SYSTEMS SALEM GENERATING STATION NO. 2 FACILITY OPERATING LICENSE DPR-75 DOCKET NO. 50-311

Gentlemen:

By letter dated August 19, 1997 (Our Ref. LR-N970543; LCR 97-19), Public Service Electric & Gas (PSE&G) Company requested a revision to the Technical Specifications (TS) for Salem Generating Station Unit No. 2. This request was made on an exigent basis. The paragraph below contains additional clarifying information relative to the exigent nature of the request.

Salem Unit 2 commenced a reactor startup on August 17, 1997, following an extended shutdown. Although Rod Position Indication (RPI) calibration has been a recognized problem, PSE&G took significant steps in trying to avoid some of these difficulties. These difficulties (curve linearity and thermal effects) were discussed in Attachment 1 of our August 19, letter.

In early August, PSE&G, in conjunction with vendor recommendations and participation, revised the calibration procedures to more closely reflect the original Westinghouse calibration procedures. The RPI system was successfully calibrated and Unit 2 went critical on August 17, 1997. On August 18, during performance of reactor physics testing (rod swap), two control rods deviated from their group demand counter by 13 steps or one step over the limit. Salem Unit 2 entered Technical Specification Limiting Condition for Operation 3.1.3.2.1. As a result of the rod position indication being greater than ± 12 steps, Salem Unit 2 completed a Technical Specification 3.1.3.2.1 required shutdown on August 19, 1997.

9708240250 970820 PDR ADDCK 05000311 P PDR



Investigation onto this apparent misalignment did not indicate any deficiencies with the calibration or circuitry. Therefore prior to August 19, 1997, PSE&G could have not forseen the need to expedite this change, and requests exigent approval of these changes to provide for an orderly startup and preclude unwarranted power transients associated with a Technical Specification required shutdown at Salem Unit 2.

Should you have any questions regarding this request, we will be pleased to discuss them with you.

Sincerely,

D. R. Powell

Director - Licensing / Regulation

and Fuels

C Mr. H. J. Miller, Administrator - Region I U. S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Mr. L. Olshan, Licensing Project Manager - Salem U. S. Nuclear Regulatory Commission One White Flint North 11555 Rockville Pike Mail Stop 14E21 Rockville, MD 20852

Ms. M. Evans (X24) USNRC Senior Resident Inspector - Salem

Mr. K. Tosch, Manager IV Bureau of Nuclear Engineering 33 Arctic Parkway CN 415 Trenton, NJ 08625