

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO:

FROM:

DATE OF DOCUMENT

DATE RECEIVED

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP INPUT FORM

NUMBER OF COPIES RECEIVED

DESCRIPTION

PLANT NAME:

ENCLOSURE

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:	<i>Ziemann</i>
W/3 CYS FOR ACTION	
LIC. ASST.:	<i>Riess</i>
W/1 CYS	
ACRS <i>16</i> CYS HOLDING/SENT <i>As CAPB</i>	

INTERNAL DISTRIBUTION

<u>REG FILE</u>			
NRC PDR			
I & E (2)			
MIPC			
SCHROEDER/IPPOLITO			
HOUSTON			
NOVAK/CHECK			
GRIMES			
CASE			
BUTLER			
HANAUER			
TEDESCO/MACCARY			
EISENHUT			
BAER			
SHAO			
VOLLMER/BURCH			
KREGER/J. COLLINS			

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: <i>Ft Pierce, Fla</i>			
TIC:			
NSIC:			

770760166

GP 104

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

TO: Mr. Norman C. Moseley

FROM: Florida Power & Light Co.  
Miami, Fla. XXXXX 33101  
A.D. Schmidt.

DATE OF DOCUMENT  
3-7-77

DATE RECEIVED  
3-17-77

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 CC

DESCRIPTION Ltr trans the following: (1P)

ENCLOSURE Lic. Event Report 77-7 occurring on 2-7-77 regarding the control circuit logic module having a bad relay in the CEA #7.....(2P)  
(1 cy encl rec'd)

**DO NOT REMOVE**

**ACKNOWLEDGED**

PLANT NAME: St. Lucie Unit 1

DHL

**SAFETY**

**FOR ACTION/INFORMATION**

**ENVIRO**

ASSIGNED AD:		ASSIGNED AD:
BRANCH CHIEF:		BRANCH CHIEF:
PROJECT MANAGER:		PROJECT MANAGER:
LIC. ASST. :		LIC. ASST. :

**INTERNAL DISTRIBUTION**

REG FILE	SYSTEMS SAFETY	PLANT SYSTEMS	SITE SAFETY &
NRC PDR	HEINEMAN	TEDESCO	ENVIRO ANALYSIS
I & E	SCHROEDER	BENAROYA	DENTON & MULLER
OELD		LAINAS	
GOSSICK & STAFF	ENGINEERING	IPPOLITO	ENVIRO TECH.
MIPC	MACARRY	KIRKWOOD	ERNST
CASE	BOSNAK		BALLARD
HANAUER	SIHWEIL	OPERATING REACTORS	YOUNGBLOOD
HARLESS	PAWLICKI	STELLO	
			SITE TECH.
PROJECT MANAGEMENT	REACTOR SAFETY	OPERATING TECH.	GAMMILL
BOYD	ROSS	EISENHUT	STAPP
P. COLLINS	NOVAK	SHAO	HULMAN
HOUSTON	ROSZTOCZY	BAER	
PETERSON	CHECK	BUTLER	SITE ANALYSIS
MELTZ		GRIMES	VOLLMER
HELTEMES	AT & I		BUNCH
SKOVHOLT	SALTZMAN		J. COLLINS
	RUTBERG		KREGER

**EXTERNAL DISTRIBUTION**

**CONTROL NUMBER**

LPDR:	NAT. LAB:	BROOKHAVEN NAT. LAB.	770760166
TIC:	REG V. IE	ULRIKSON (ORNL)	
NSIC:	LA PDR		
ASLB:	CONSULTANTS:		
ACRS CYS HOLDING/SENT			

1950

1950


1950

1950

1950

1950

1950



March 7, 1977

PRN-LI-77-60

**REGULATORY DOCKET FILE COPY**

Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 1217  
Atlanta, Georgia 30303



Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-77-7  
ST. LUCIE UNIT 1  
DATE OF OCCURRENCE: FEBRUARY 7, 1977

CEA 7

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

*A. D. Schmidt*  
A. D. Schmidt  
Vice President  
Power Resources

MAS/cpc


Attachment

cc: Robert Lowenstein; Esquire  
Director, Office of Inspection and Enforcement (30)  
Director, Office of Management Information and  
Program Control (3)

7707 60/66

CHANGES






REPORTABLE OCCURRENCE 335-77-7  
LICENSEE EVENT REPORT  
PAGE TWO

Event Description (Continued)

inoperable CEA (see LER 335-76-25), but the first event was due to failure of integrated circuit components. The two events are not considered to be generically related. (335-77-7)





March 7, 1977

PRN-LI-77-60

Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 1217  
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-77-7  
ST. LUCIE UNIT 1  
DATE OF OCCURRENCE: FEBRUARY 7, 1977

CEA 7

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.


Very truly yours,

A. D. Schmidt  
Vice President  
Power Resources


MAS/cpc

Attachment

cc: Robert Lowenstein, Esquire  
Director, Office of Inspection and Enforcement (30)  
Director, Office of Management Information and  
Program Control (3)







REPORTABLE OCCURRENCE 335-77-7  
LICENSEE EVENT REPORT  
PAGE TWO

Event Description (Continued)

inoperable CEA (see LER 335-76-25), but the first event was due to failure of integrated circuit components. The two events are not considered to be generically related. (335-77-7)