

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO:
Mr. Norman C. Moseley

FROM:
Florida Power & Light Company
Miami, Florida
A. D. Schmidt

DATE OF DOCUMENT
8/26/76

DATE RECEIVED
9/8/76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
One signed copy

DESCRIPTION

Ltr. trans the following:

(1-P)

PLANT NAME:
St. Lucie #1

ENCLOSURE

Licensee Event Report (RO 50-335/76-43) on 8/13/76 concerning three stand pipes being found missing in the "A" S/G during a special inspection of Steam Generators "A and "B".

(2-P) **ACKNOWLEDGED**
DO NOT REMOVE

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 9/9/76 RJL

BRANCH CHIEF: Ziemann

W/3 CYS FOR ACTION

LIC. ASST.: Diggs

W/1 CYS

ACRS /6 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

- REG FILE
- NRC PDR
- I & E (2)
- MIPC
- SCHROEDER/IPPOLITO
- HOUSTON
- NOVAK/CHECK
- GRIMES
- CASE
- BUTLER
- HANAUER
- TEDESCO/MACCARY
- EISENHUT
- BAER
- SHAO
- VOLLMER/BUNCH
- KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: Ft. Pierce, Fla.

TIC:

NSIC:

CONTROL NUMBER

9160

28

1. The first part of the document discusses the importance of maintaining accurate records of all transactions.

2. It is essential to ensure that all data is entered correctly and that any discrepancies are identified and corrected promptly.

3. The following table provides a summary of the key findings from the analysis.


4. In conclusion, the results indicate that there is a significant need for improved data management practices.

50-335



August 26, 1976
PRN-LI-76-230

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N.W., Suite 818
Atlanta, Georgia 30303



Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-43
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: AUGUST 13, 1976

STEAM GENERATOR FEED RING

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide prompt notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
A. D. Schmidt
Vice President
Power Resources

RSA/bfp

Attachment

REGULATORY DOCKET FILE COPY




cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (40)
Director, Office of Management Information and
Program Control (3)

9160

Reportable Occurrence 335-76-43
Licensee Event Report
Page Two

Event Description (continued)

discrepancies were noted in the "B" S/G. FP&L and C.E. personnel are currently evaluating data in order to determine component modifications. Preliminary evaluation of the removed stand pipes indicate cyclic fatigue and failure. Current plans are to make the planned component modifications during the current fuel inspection shutdown. (335-76-43)



August 26, 1976
PRN-LI-76-230

Mr. Norman C. Moseley, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N.W., Suite 818
Atlanta, Georgia 30303



Dear Mr. Moseley:

REPORTABLE OCCURRENCE 335-76-43
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: AUGUST 13, 1976

STEAM GENERATOR FEED RING

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide prompt notification of the subject occurrence.

Very truly yours,

A handwritten signature in cursive script, appearing to read "A. D. Schmidt".


A. D. Schmidt
Vice President
Power Resources

RSA/bfp

Attachment

cc: Jack R. Newman, Esquire
Director, Office of Inspection and Enforcement (40)
Director, Office of Management Information and
Program Control (3)

9691



LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE				EVENT TYPE									
01	F	L	S	L	S	I	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1	
7	8	9	14	15	25	26	30	31	32																
CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE				REPORT DATE									
01	CONT			T	L	0	5	0	-	0	3	3	5	0	8	1	3	7	6	0	8	2	4	7	6
7	8	57	58	59	60	61	68	69	74	75	80														

EVENT DESCRIPTION

02	During a special inspection of Steam Generators "A" and "B" in order to																							80
03	accomplish tack welding of the stand pipes for the feed ring, three stand																							80
04	pipes were found missing in the "A" S/G. The missing stand pipes were																							80
05	retrieved and one further stand pipe was removed for inspection and																							80
06	analysis. No other discrepancies were found in the "A" S/G. No																							80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION		
07	C	H	F	H	T	E	X	C	H	N	C	4	9	0	N	
7	8	9	10	11	12	17	43	44	47	48						

CAUSE DESCRIPTION

08	The resolution is not known at this time. FP&L is currently awaiting																							80
09	completion of testing being performed by vendor personnel.																							80
10																								80

FACILITY STATUS		% POWER			OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
11	I	0	0	0	N/A				C	N/A				
7	8	9	10	12	13	44	45	46	80					
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE						
12	Z	Z	N/A				N/A							
7	8	9	10	11	44	45	80							

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION											
13	0	0	0	Z	N/A										
7	8	9	11	12	13	80									

PERSONNEL INJURIES

NUMBER		DESCRIPTION												
14	0	0	0	N/A										
7	8	9	11	12	80									

PROBABLE CONSEQUENCES

15	N/A																							80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION -None - since plant shutdown for fuel inspection and steam generator work is not expected to last longer than fuel inspection.																					80
16	Z																						80
7	8	9	10																				80

PUBLICITY

17	N/A																							80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	See Page Two for continuation of Event Description.																							80
----	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: R. S. Abraham

PHONE: (305) 552-3779

1. A. G.

17

Event Description (continued)

discrepancies were noted in the "B" S/G. FP&L and C.E. personnel are currently evaluating data in order to determine component modifications. Preliminary evaluation of the removed stand pipes indicate cyclic fatigue and failure. Current plans are to make the planned component modifications during the current fuel inspection shutdown. (335-76-43)

U.S. A.E.C.
REGULATORY OPERATIONS
REGION II
ATLANTA, GA.

DEC 30 11 09 AM '76