

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 V A S P S 2 20 p f p p p p - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

01 REPORT SOURCE L 605 p p p p p p 7 0 2 0 8 7 9 8 0 3 0 7 7 9 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On 2/8/79, while performing PT-39B-1, the mechanic performing the inspection dis-
03 covered three snubbers that were not listed on the PT. Further investigation reveal-
04 ed that the three snubbers had not been visually inspected during the previous per-
05 formance of either PT-39B-1 or PT-39A-1. This is contrary to T.S. 4.1.7A. Upon dis-
06 covery, the three snubbers were inspected and determined operable. Therefore, the
07 health and safety of the public were not affected.
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
Z Z 11 D 12 Z 13 S U P O R T 14 D 15 Z 16
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
7 8 9 21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 G 19 Z 20 0 0 0 22 Y 23 N 24 N 25 I 2 0 7 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The three snubbers were inadvertantly omitted from both PT-39B-1 and PT-39A-1 when the
11 PT's were changed on August 18, 1979. The snubbers were added to PT-39B-1 and inspect-
12 ed. A request to change procedure has been initiated to permanently add the subject
13 snubbers (2-SI-HSS-21, 2-SI-HSS-24, 2-SI-HSS-27) to both PT's.
14

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
H 0 0 0 29 NA B 31 Mechanic's observation
16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 33 Z 34 NA NA
17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 NA
18 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 NA
19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 NA
20 PUBLICITY ISSUED DESCRIPTION 45
N 44 NA

7903130353

NRC USE ONLY

W. L. Stewart

(804) 357-3184

NAME OF PREPARER

PHONE

GPO 917-926

Surry Power Station
Docket No.: 50-281
Report No.: 79-009/03L-0
Event Date: 2/8/79

Snubbers Not Inspected

1.) Description of Event:

On 2/8/79, while performing PT-39B-1 (Accessible Snubbers - Visual Inspection-As Found), the mechanic performing the inspection discovered three snubbers that were not listed on the PT. Further investigation revealed that the three snubbers had not been visually inspected during the previous performance of either PT-39B-1 or PT-39A-1 (Accessible Snubbers Visual Inspection - As Left). This is contrary to Tech. Spec. 4.1.7.A and reportable in accordance with Tech. Spec. 6.6.2.b.(3). The subject snubbers are 2-SI-HSS-21, 2-SI-HSS-24, and 2-SI-HSS-27.

2.) Probable Consequences/Status of Redundant Systems:

Upon discovery, the three snubbers were inspected and determined operable. The health and safety of the general public were not affected.

3.) Cause of Event:

The three snubbers were inadvertently omitted from both PT-39B-1 and PT-39A-1 when the PT's were changed on August 18, 1978.

4.) Immediate Corrective Action:

The three snubbers were added to PT-39B-1 and inspected. The snubbers were determined operable in accordance with the visual inspection criteria stipulated in the PT.

5.) Scheduled Corrective Action:

A request to change procedure has been initiated to permanently add the subject snubbers to both PT-39B-1 and PT-39A-1.

6.) Action Taken to Prevent Recurrence:

A thorough review of all snubber PT's for both Unit 1 and Unit 2 has been performed. The subject three snubbers were the only ones that were omitted.

7.) Generic Implications:

Since this is considered a random event, there are no generic implications.