

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

August 14, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

Serial No. 636  
LQA/ESG:esh


Docket Nos. 50-280  
50-281  
50-338  
50-339

Dear Mr. O'Reilly:

On July 19, 1979, by letter Serial No. 235B, we sent a final report to Region II concerning failure of Inside Recirculation Spray Pump Motors at North Anna 2, and describing modifications made to the motors to prevent further similar problems. We indicated that environmental qualification of these motors would be reverified, and a General Electric topical report submitted.

This report has now been completed, and is enclosed for your information. Based on the data in the report, it is concluded that the modifications will not affect the previously demonstrated qualification of the inside recirculation spray pump motors for the Surry and North Anna Power Stations.

Very truly yours,



Sam C. Brown, Jr.  
Senior Vice President-Power Station  
Engineering and Construction

Enclosures

cc: Mr. Victor Stallo, Director  
Office of Inspection and Enforcement

Mr. Harold R. Denton, Director (10 copies)  
Office of Nuclear Reactor Regulation

7908160 467

Boo  
1/5  
ADD:  
TA/EDD  
AD/SXS & PROJ  
ENR BR  
REAR SETY BR  
PLANT SYS BR  
EEB  
CHANGE  
BC  
44