

Central Pines

VIRGINIA ELECTRIC AND POWER COMPANY

USNRC REG.
LNTA.

19 JUL 13 A 7:36

Mr. James P. O'Reilly
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Surry Power Station
P. O. Box 315
Surry, Virginia 23883

July 12, 1979

Docket No: 50-280

J. P. O'REILLY
~~_____~~
C. M. UPRIGHT
P. D. CHENDEN
W. B. KENNA
F. J. LONG
C. E. MURPHY
J. T. SUTHERLAND
K. M. CLARK

Lewis
Terrific

Dear Sir:

In accordance with the provisions of Item 4, I.R. Bulletin No. 79-13, VEPICO submits the following report for Surry Power Station:

With radiography of all feedwater welds inside containment in progress and 50% complete, two rejectable indications have been found to date. Specifically, 'B' S.G. Feedwater Line (14-WFPD-13-601) Weld #1 has a small area of rejectable porosity. 'A' S.G. Feedwater Line (14-WFPD-17-601) Weld #13 has small areas of rejectable incomplete fusion..

©

*act
CP*

Very truly yours,

O. L. Stewart

W. L. Stewart
Station Manager

Q
6/27/80 10:16 AM
2862