

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

December 4, 1979

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
Attn: Mr. A. Schwencer, Chief
Operating Reactors Branch #1
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Serial No. 920/102979
PO/FHT:baw
Docket Nos: 50-280
50-281
License Nos: DPR-32
DPR-37

Dear Mr. Denton:

SURRY POWER STATION UNITS 1 AND 2
CONTROL ROD POSITION INDICATION SYSTEMS

In response to your letter of October 29, 1979, on the above subject, we have reviewed our present Technical Specification surveillance requirements. Our present Technical Specifications specify that rod-out-of-alignment action is to be taken if a control rod is more than 15 inches out of alignment with its bank. The surveillance procedures in effect at Surry Power Station currently require corrective action when the rod position indication reaches or exceeds 12 steps difference. Thus compliance with the requirement for alignment within 15 inches has been maintained.

As requested in your letter, a change to the Technical Specifications is being prepared to ensure that the control rods are required to be maintained within + 12 steps from the group step counter demand position. This change will eliminate any ambiguity in interpreting the requirement to maintain the control rod positions within + 12 steps.

If you have any questions or require additional information, please contact this office.

Very truly yours,

C. M. Stallings

C. M. Stallings
Vice President-Power Supply
and Production Operations

cc: Mr. James P. O'Reilly
Office of Inspection and Enforcement
Region II

7912100302

Aoo'
s
1/0