

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)**

CONTROL NO: 3144

FILE: INCIDENT REPORT FILE

FROM: Rochester Gas & Elec. Co. Rochester, N.Y. L.D. White			DATE OF DOC 3-17-75	DATE REC'D 3-24-75	LTR XX	TWX	RPT	OTHER
TO: J.P. O'Reilly			ORIG None	CC	OTHER	SENT AEC PDR <u>XXX</u> SENT LOCAL PDR <u>XXX</u>		
CLASS	UNCLASS XX	PROP INFO	INPUT	NO CYS REC'D 30	DOCKET NO: 50-244			

**DESCRIPTION:**  
Ltr. reporting abnormal occurr. # 75-01  
trans the following...  
  
PLANT NAME: RE Ginna #1

**ENCLOSURES:**  
Abnormal Occurr. concerning drop of two  
control rods...  
  
**ACKNOWLEDGED  
DO NOT REMOVE**

FOR ACTION/INFORMATION VCR 3-24-75

- |                         |                            |                             |                        |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L)<br>W/ Copies | SCHWENCER (L)<br>W/ Copies | ZIEMANN (L)<br>W/ Copies    | REGAN (E)<br>W/ Copies |
| CLARK (L)<br>W/ Copies  | STOLZ (L)<br>W/ Copies     | DICKER (E)<br>W/ Copies     | LEAR (L)<br>W/ Copies  |
| PARR (L)<br>W/ Copies   | VASSALLO (L)<br>W/ Copies  | KNIGHTON (E)<br>W/ Copies   | SPELS<br>W/ Copies     |
| KNIEL (L)<br>W/ Copies  | PURPLE (L)<br>W/ Copies    | YOUNGBLOOD (E)<br>W/ Copies |                        |

**INTERNAL DISTRIBUTION**


- |   |   |  |   |  |
|---|---|--|---|--|
| <u>REG FILE</u><br>NRC PDR<br>OGC, ROOM P-506A<br>GOSSICK/STAFF<br>CASE<br>GIAMBUSSO<br>BOYD<br>MOORE (L)<br>DEYOUNG (L)<br>SKOVHOLT (L)<br>GOLLER (L) (Ltr)<br>P. COLLINS<br>DENISE<br>REG OPR<br>FILE & REGION (2)<br>T.R. WILSON (3)<br>STEELE | TECH REVIEW<br>SCHROEDER<br>MACCARY<br>KNIGHT<br>PAWLICKI<br>SHAO<br>**STELLO<br>**HOUSTON<br>**NOVAK<br>ROSS<br>IPPOLITO<br>TEDESCO<br>LONG<br>LAINAS<br>BENAROYA<br>VOLLMER | DENTON<br>**GRIMES<br>GAMMILL<br>KASTNER<br>BALLARD<br>SPANGLER<br><br>ENVIRO<br>MULLER<br>DICKER<br>KNIGHTON<br>YOUNGBLOOD<br>REGAN<br>PROJECT LDR<br><br>HARLESS | LIC ASST<br>R. DIGGS (L)<br>H. GEARIN (L)<br>E. GOULBOURNE (L)<br>P. KREUTZER (E)<br>J. LEE (L)<br>M. MAIGRET (L)<br>S. REED (E)<br>M. SERVICE (L)<br>S. SHEPPARD (L)<br>M. SLATER (E)<br>H. SMITH (L)<br>S. TEETS (L)<br>G. WILLIAMS (E)<br>V. WILSON (L)<br>R. INGRAM (L) | A/T IND.<br>BRAITMAN<br>SALTZMAN<br>MELTZ<br><br>PLANS<br>MCDONALD<br>CHAPMAN<br>DUBE (Ltr)<br>E. COUPE<br>PETERSON<br>HARTFIELD (2)<br>KLECKER<br>EISENHUT<br>WIGGINTON<br>F. WILLIAMS<br>HANAUER |
|---|---|--|---|--|

**EXTERNAL DISTRIBUTION**

- |   |                                |   |
|---|--------------------------------|---|
| 1 - LOCAL PDR Lyons, N.Y. & Rochester, N.Y. | 1 - NATIONAL LABS              | 1 - PDR-SAN/LA/NY                       |
| 1 - TIC (ABERNATHY) (1)(2)(10)              | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB                  |
| 1 - NSIC (BUCHANAN)                         | 1 - CONSULTANTS                | 1 - G. ULRIKSON, ORNL                   |
| 1 - ASLB                                    | NEWMARK/BLUME/AGBABIAN         | 1 - AGMED (RUTH GUSSMAN)<br>Rm B-127 GT |
| 1 - Newton Anderson                         |                                | 1 - J. D. RUNKLES, Rm E-201<br>GT       |
| 5 - ACRS SENT TO LIC ASST                   |                                |   |
| ** SEND ONLY TEN DAY REPORTS                |                                |   |




# REGULATORY DOCKET FILE COPY



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649



LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700



March 17, 1975

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406



Subject: Unusual Event 75-01, Drop of two control rods.  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.6.2b, the attached report of Unusual Event 75-01 is hereby submitted. Two additional copies of this letter and the attachment are enclosed.


Very truly yours,

*L. D. White, Jr.*  
L. D. White, Jr.

Attachment

cc: Mr. Donald F. Knuth (30)

3144



# LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01   N   Y   R   E   G   I   1   1   1   1   1   1   1   1														LICENSE NUMBER 0   0   -   0   0   0   0   0   -   0   0   0   0   0   0										LICENSE TYPE 4   1   1   1   1   1					EVENT TYPE 0   3	
CATEGORY 01   CONT		REPORT TYPE M   I		REPORT SOURCE L   L		DOCKET NUMBER 0   5   0   -   0   2   4   4							EVENT DATE 0   3   0   5   7   5					REPORT DATE 0   3   1   7   7   5												

### EVENT DESCRIPTION

02 | During core boring of floor above rod control cabinets, turbine runback to 70% occurred; B bank group 2 rcc's G5 & G9 were at bottom of core. With unit at hot shutdown, after inspection B bank was exercised 0-20 steps twice verifying operability. G5 & G9 had dropped on a previous occasion of water leak over cabinets. (Unusual Event 50-244/75-01).

SYSTEM CODE R   B		CAUSE CODE F		COMPONENT CODE C   O   N   R   O   D				PRIME COMPONENT SUPPLIER N		COMPONENT MANUFACTURER W   1   2   0			VIOLATION N	
----------------------	--	-----------------	--	---	--	--	--	-------------------------------	--	---	--	--	----------------	--

### CAUSE DESCRIPTION

08 | A water hose for boring machine broke at coupling. Water drained thru 2 new holes to top of rod control cabinets, grounding out control power for stationary grippers for rcc's G5 & G9, allowing them to drop. Core openings were covered; precautionary instruc-

FACILITY STATUS E		% POWER 1   0   0			OTHER STATUS NA				METHOD OF DISCOVERY a		DISCOVERY DESCRIPTION Rod Bottom Alarm			
----------------------	--	----------------------	--	--	--------------------	--	--	--	--------------------------	--	---	--	--	--

FORM OF ACTIVITY RELEASED Z		CONTENT OF RELEASE Z		AMOUNT OF ACTIVITY NA				LOCATION OF RELEASE NA			
--------------------------------	--	-------------------------	--	--------------------------	--	--	--	---------------------------	--	--	--

### PERSONNEL EXPOSURES

NUMBER 0   0   0			TYPE Z		DESCRIPTION NA			
---------------------	--	--	-----------	--	-------------------	--	--	--

### PERSONNEL INJURIES

NUMBER 0   0   0			DESCRIPTION NA			
---------------------	--	--	-------------------	--	--	--

### OFFSITE CONSEQUENCES

15 | NA

### LOSS OR DAMAGE TO FACILITY

TYPE Z		DESCRIPTION NA			
-----------	--	-------------------	--	--	--

### PUBLICITY

17 | NA

### ADDITIONAL FACTORS Cause Description cont'd.

18 | tions were given to job personnel working above rod control cabinets.

19 |

NAME: Charles E. Platt PHONE: 315-524-5351