

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)**

CONTROL NO: 10806

FILE: INCIDENT REPORT FILE

FROM: Rochester Gas & Elec Co Rochester, NY L D White Jr		DATE OF DOC 10-1-75	DATE REC'D 10-14-75	LTR XXX	TWX	RPT	OTHER
TO: Mr O'Reilly		ORIG one signed	CC	OTHER	SENT AEC PDR <u>XX</u>		SENT LOCAL PDR <u>XX</u>
CLASS	UNCLASS XXXXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-244		

DESCRIPTION:  
Ltr trans the following:

ENCLOSURES:  
Abnormal Occurrence #75-8 on 9-17-75 concern-  
ing the failure of the PT-1 rod control system  
.....(1 cy encl rec'd)

**DO NOT REMOVE  
ACKNOWLEDGED**

PLANT NAME: R E Ginna

FOR ACTION/INFORMATION 10-16-75 ehf

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

**INTERNAL DISTRIBUTION**

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER  <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR  HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ  <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	---	---	--

**EXTERNAL DISTRIBUTION**

1 - LOCAL PDR <u>Waukegan, I //</u>	1 - TIC (ABERNATHY) (1)(2)(10)	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - NSIC (BUCHANAN)	1 - ASLB	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - Newton Anderson	1 - ACRS SENT TO LIC ASST <u>Shappard</u>	1 - CONSULTANTS NEWMARK/BLUME/AGBABIAN	1 - G. ULRIKSON, ORNL
** SEND ONLY TEN DAY REPORTS			1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
			1 - J. D. RUNKLES, Rm E-201 GT

40



-----

-----

-----  
-----  
-----

-----

-----

-----

-----


-----

-----

-----



REGULATORY DOCKET FILE COPY




ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700

October 1, 1975



Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Subject: Unusual Event 75-08, Control rod G-5 lift coil open circuit  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:


In accordance with Technical Specifications, Article 6.6.2b, the attached report of Unusual Event 75-08 is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,


L. D. White, Jr.

Attachment

cc: Mr. Donald F. Knuth (30)  
Mr. William G. McDonald (3)



10806



**LICENSEE EVENT REPORT**

[PLEASE PRINT ALL REQUIRED INFORMATION]

CONTROL BLOCK:         
1 6

LICENSEE NAME: 01 NYREG1      
7 8 9 14

LICENSE NUMBER: 00-0000000-00      
15 25

LICENSE TYPE: 411111  
26 30

EVENT TYPE: 03  
31 32

REPORT TYPE: 01 CONT PO     
7 8 57 58

REPORT SOURCE: LL  
59 60

DOCKET NUMBER: 050-0244  
61 68

EVENT DATE: 091775  
69 74

REPORT DATE: 100175  
75 80

EVENT DESCRIPTION

02 During performance of PT-1 Rod Control System, RPI indicated rod G-5 in bank B not  
7 8 9 80

03 moving with bank. All other rods moved and met requirements of PT-1. Bank rods were  
7 8 9 80

04 returned to normal full out position. Investigation showed RPI's functioning properly,  
7 8 9 80

05 G-5 was apparently not receiving signal to move, and normal rod drop would not be  
7 8 9 80

06 impeded upon trip signal. (Unusual Event 50-244/75-08)  
7 8 9 80

SYSTEM CODE: 07 RB     
7 8 9 10

CAUSE CODE: E  
11

COMPONENT CODE: CRDRVE     
12 17

PRIME COMPONENT SUPPLIER: N  
43

COMPONENT MANUFACTURER: W120  
44 47

VIOLATION: N  
48

CAUSE DESCRIPTION

08 G-5 lift coil open circuit in the cable or coil prevented its functioning in the normal  
7 8 9 80

09 driving of G-5. The PORC determined G-5 inoperable and that continued unit operation  
7 8 9 80

10 is allowed, per Tec. Spec. 3.10. The PORC recommended (cont'd. on attached sheet)  
7 8 9 80

FACILITY STATUS: 11 E  
7 8 9

% POWER: 100  
10 12 13

OTHER STATUS: NA  
44

METHOD OF DISCOVERY: b  
45

DISCOVERY DESCRIPTION: NA  
46 80

FORM OF ACTIVITY RELEASED: 12 Z  
7 8 9

CONTENT OF RELEASE: Z  
10 11

AMOUNT OF ACTIVITY: NA  
44

LOCATION OF RELEASE: NA  
45 80

PERSONNEL EXPOSURES

NUMBER: 13 000     
7 8 9 11

TYPE: Z  
12

DESCRIPTION: NA  
13 80

PERSONNEL INJURIES

NUMBER: 14 000  
7 8 9 11

DESCRIPTION: NA  
12 80

OFFSITE CONSEQUENCES

15 NA  
7 8 9 80

LOSS OR DAMAGE TO FACILITY

TYPE: 16 Z  
7 8 9 10

DESCRIPTION: NA  
80

PUBLICITY

17 NA  
7 8 9 80

ADDITIONAL FACTORS

18 Bank B is not a controlling bank.  
7 8 9 80

19  
7 8 9 80

NAME: Bruce A. Snow PHONE: 716/546-2700, ext. 291-214



Handwritten mark or signature at the top right.

Handwritten mark or signature below the top right mark.

Licensee Event Report  
Unusual Event 50-244/75-08

Cause Description (cont'd.)

approval and use of EM-149 Check Out Lift Circuitry for Control Rod G-5 in 2BD Power Cabinet and repair of the identified fault at the earliest convenient outage.

This action will be documented in Correction Action Report CAR-1042.



Handwritten scribble or signature in the top right corner.

.....