

REPORT OF ABNORMAL OCCURRENCE AND/OR INCIDENT

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)

CONTROL NO: 10586

FILE: INCIDENT REPORT FILE

FROM: Rochester Gas & Electric Rochester, N.Y. L.D. White, Jr.		DATE OF DOC 10-1-75	DATE REC'D 10-6-75	LTR XXX	TWX	RPT	OTHER
TO: Mr. James P. O'Reilly		ORIG None	CC 30	OTHER	SENT AEC PDR SENT LOCAL PDR		XXX XXX
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 30	DOCKET NO: 50-244		
DESCRIPTION: Letter trans the following.....				ENCLOSURES: Unusual Evnet # 75-08, on 9-17-75, Concerning an inoperable Control rod G-5 lift coil open circuit..... ( 30 Copies Enclosure Received)			
PLANT NAME: RE Ginna # 1							

FOR ACTION/INFORMATION

SAB 10-7-75

- |                         |                            |                             |                        |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L)<br>W/ Copies | SCHWENCER (L)<br>W/ Copies | ZIEMANN (L)<br>W/ Copies    | REGAN (E)<br>W/ Copies |
| CLARK (L)<br>W/ Copies  | STOLZ (L)<br>W/ Copies     | DICKER (E)<br>W/ Copies     | LEAR (L)<br>W/ Copies  |
| PARR (L)<br>W/ Copies   | VASSALLO (L)<br>W/ Copies  | KNIGHTON (E)<br>W/ Copies   | SPELS<br>W/ Copies     |
| KNIEL (L)<br>W/ Copies  | PURPLE (L)<br>W/3 Copies   | YOUNGBLOOD (E)<br>W/ Copies | W/ Copies              |

**ACKNOWLEDGED**  
**DO NOT REMOVE**

INTERNAL DISTRIBUTION

- |   |  |  |   |  |
|---|--|--|---|--|
| <u>REG FILE</u><br>NRC PDR<br>OGC, ROOM P-506A<br>GOSSICK/STAFF<br>CASE<br>GIAMBUSSO<br>BOYD<br>MOORE (L)<br>DEYOUNG (L)<br>SKOVHOLT (L)<br>GOLLER (L) (Ltr)<br>P. COLLINS<br>DENISE<br>REG OPR<br>FILE & REGION (2)<br>MIPC/PE (3)<br>STEELE | <u>TECH REVIEW</u><br>SCHROEDER<br>MACCARY<br>KNIGHT<br>PAWLICKI<br>SHAO<br>**STELLO<br>**HOUSTON<br>**NOVAK<br>ROSS<br>IPPOLITO<br>TEDESCO<br>J. COLLINS<br>LAINAS<br>BENAROYA<br>VOLLMER | <u>DENTON</u><br>**GRIMES<br>GAMMILL<br>KASTNER<br>BALLARD<br>SPANGLER<br><br><u>ENVIRO</u><br>MULLER<br>DICKER<br>KNIGHTON<br>YOUNGBLOOD<br>REGAN<br>PROJECT LDR<br>HARLESS | <u>LIC ASST</u><br>R. DIGGS (L)<br>H. GEARIN (L)<br>E. GOULBOURNE (L)<br>P. KREUTZER (E)<br>J. LEE (L)<br>M. RUSHBROOK (L)<br>S. REED (E)<br>M. SERVICE (L)<br>S. SHEPPARD (L)<br>M. SLATER (E)<br>H. SMITH (L)<br>S. TEETS (L)<br>G. WILLIAMS (E)<br>V. WILSON (L)<br>R. INGRAM (L)<br>M. DUNCAN (E) | <u>A/T IND.</u><br>BRAITMAN<br>SALTZMAN<br>MELTZ<br><br><u>PLANS</u><br>MCDONALD<br>CHAPMAN<br>DUBE (Ltr)<br>E. COUPE<br>PETERSON<br>HARTFIELD (2)<br>KLECKER<br>EISENHUT<br>WIGGINTON<br>F. WILLIAMS<br>HANAUER |
|---|--|--|---|--|

EXTERNAL DISTRIBUTION

- |                                       |                                |   |
|---------------------------------------|--------------------------------|---|
| 1 - LOCAL PDR Lyons & Rochester, N.Y. | 1 - NATIONAL LABS              | 1 - PDR-SAN/LA/NY                       |
| 1 - TIC (ABERNATHY) (1)(2)(10)        | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB                  |
| 1 - NSIC (BUCHANAN)                   | 1 - CONSULTANTS                | 1 - G. ULRIKSON, ORNL                   |
| 1 - ASLB                              | NEWARK/BLUME/AGBABIAN          | 1 - AGMED (RUTH GUSSMAN)<br>Rm B-127 GT |
| 1 - Newton Anderson                   |                                | 1 - J. D. RUNKLES, Rm E-201<br>GT       |
| 5 - ACRS SENT TO LIC ASST S. Sheppard |                                |   |
| ** SEND ONLY TEN DAY REPORTS          |                                |   |

AO-4 [Signature]

1000000000



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

Regulatory


File Cycle  
TELEPHONE

AREA CODE 716 546-2700



October 1, 1975

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406



Subject: Unusual Event 75-08, Control rod G-5 lift coil open circuit  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.6.2b, the attached report of Unusual Event 75-08 is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,


L. D. White, Jr.

Attachment

cc: Mr. Donald F. Knuth (30)  
Mr. William G. McDonald (3)



10586



# LICENSEE EVENT REPORT

CONTROL-BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 N Y R E G 1      LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0      LICENSE TYPE: 4 1 1 1 1      EVENT TYPE: 0 3

CATEGORY: 01 CONT      REPORT TYPE: P O      REPORT SOURCE: L      DOCKET NUMBER: 0 5 0 - 0 2 4 4      EVENT DATE: 0 9 1 7 7 5      REPORT DATE: 1 0 0 1 7 5

### EVENT DESCRIPTION

02 During performance of PT-1 Rod Control System, RPI indicated rod G-5 in bank B not  
03 moving with bank. All other rods moved and met requirements of PT-1. Bank rods were  
04 returned to normal full out position. Investigation showed RPI's functioning properly,  
05 G-5 was apparently not receiving signal to move, and normal rod drop would not be  
06 impeded upon trip signal. (Unusual Event 50-244/75-08)

SYSTEM CODE: 07 R B      CAUSE CODE: E      COMPONENT CODE: C R D R V E      PRIME COMPONENT SUPPLIER: N      COMPONENT MANUFACTURER: W 1 2 0      VIOLATION: N

### CAUSE DESCRIPTION

08 G-5 lift coil open circuit in the cable or coil prevented its functioning in the normal  
09 driving of G-5. The PORC determined G-5 inoperable and that continued unit operation  
10 is allowed, per Tec. Spec. 3.10. The PORC recommended (cont'd. on attached sheet)

FACILITY STATUS: 11 E      % POWER: 1 0 0      OTHER STATUS: NA      METHOD OF DISCOVERY: b      DISCOVERY DESCRIPTION: NA

FORM OF ACTIVITY RELEASED: 12 Z      CONTENT OF RELEASE: Z      AMOUNT OF ACTIVITY: NA      LOCATION OF RELEASE: NA

### PERSONNEL EXPOSURES

13 NUMBER: 0 0 0      TYPE: Z      DESCRIPTION: NA

### PERSONNEL INJURIES

14 NUMBER: 0 0 0      DESCRIPTION: NA

### OFFSITE CONSEQUENCES

15 NA

### LOSS OR DAMAGE TO FACILITY

16 TYPE: Z      DESCRIPTION: NA

### PUBLICITY

17 NA

### ADDITIONAL FACTORS

18 Bank B is not a controlling bank.

19 *Duke*

NAME: Bruce A. Snow

PHONE: 716/546-2700, ext. 291-214

Licensee Event Report  
Unusual Event 50-244/75-08

Cause Description (cont'd.)

approval and use of EM-149 Check Out Lift Circuitry for Control Rod G-5 in 2BD Power Cabinet and repair of the identified fault at the earliest convenient outage.

This action will be documented in Correction Action Report CAR-1042.



1000

1000