



NORTH - SOUTH PROFILE SHOWING FRESH BEDROCK SURFACE IN THE FAULT AREA BETWEEN BORINGS 113 AND 210