

PRIORITY 1
(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9503280052 DOC.DATE: 95/03/20 NOTARIZED: NO DOCKET #
 FACIL:50-281 Surry Power Station, Unit 2, Virginia Electric & Powe 05000281
 AUTH.NAME AUTHOR AFFILIATION
 BOWLING,M.L. Virginia Power (Virginia Electric & Power Co.)
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Notifies of SG tubes plugged during 1995 refueling outage.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code - GL-89-04

NOTES: 05000281

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD2-2 LA		1	1		PD2-2 PD		1	1
	BUCKLEY, B		1	1					
INTERNAL:	ACRS		6	6		AEOD/SPD/RAB		1	1
	FILE CENTER 01		1	1		NRR/DE/EMCB		1	1
	NRR/DE/EMEB		1	1		NUDOCS-ABSTRACT		1	1
	OGC/HDS2		1	0		RES/DSIR/EIB		1	1
EXTERNAL:	LITCO BROWN, B		1	1		LITCO RANSOME, C		1	1
	NOAC		1	1		NRC PDR		1	1
NOTES:			1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
 DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 21 ENCL 20

MAF

P
R
I
O
R
I
T
Y

1

D
O
C
U
M
E
N
T

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

March 20, 1995

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Serial No. 95-118
NL/RPC
Docket No. 50-281
License No. DPR-37

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
SURRY POWER STATION UNIT 2
STEAM GENERATOR TUBE INSPECTION REPORT

Planned inservice inspection of the Surry Unit 2 "A" steam generator was completed during the 1995 refueling outage. In accordance with Surry Power Station Technical Specifications, Section 4.19.F.a, this letter provides notification of the steam generator tubes that were plugged during the outage. Four tubes were plugged due to axially oriented indications, and one tube (R1-C59) was plugged as a precautionary measure due to a restriction at the tube sheet on the hot leg which prevented inspection of the area with a rotating pancake coil probe.

"A" STEAM GENERATOR
TUBES PLUGGED

<u>ROW</u>	<u>COLUMN</u>
4	36
6	39
7	39
7	50
1	59 (precautionary)

If you have any questions concerning these results, please contact us.

Very truly yours,



M. L. Bowling, Manager
Nuclear Licensing and Programs

cc: United States Nuclear Regulatory Commission
Region II
101 Marietta Street, N. W.
Suite 2900
Atlanta, Georgia 30323

Mr. M. W. Branch
NRC Senior Resident Inspector
Surry Power Station

9503280052 950320
PDR ADOCK 05000281
Q PDR

A047
110