

# ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9304220166      DOC. DATE: 93/04/19      NOTARIZED: NO      DOCKET #  
 FACIL: 50-281 Surry Power Station, Unit 2, Virginia Electric & Power      05000281  
 AUTH. NAME      AUTHOR AFFILIATION  
 BOWLING, M.L.      Virginia Power (Virginia Electric & Power Co.)  
 RECIPIENT NAME      RECIPIENT AFFILIATION  
                                  Document Control Branch (Document Control Desk)

SUBJECT: Provides notification of SG tubes plugged during outage as precautionary measure.

DISTRIBUTION CODE: A047D      COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES: 1cy NMSS/SCDB/PM. 05000281

	RECIPIENT	COPIES	RECIPIENT	COPIES
	ID CODE/NAME	LTR ENCL	ID CODE/NAME	LTR ENCL
	PD2-2 LA	1 0	PD2-2 PD	1 1
	BUCKLEY, B	2 2		
INTERNAL:	ACRS	6 6	NRR/DE/EMEB	1 1
	NUDOCS-ABSTRACT	1 1	OC/LFMB	1 0
	OGC/HDS2	1 0	<del>REG FILE</del> 01	1 1
	RES MILLMAN, G	1 1	RES/DSIR/EIB	1 1
EXTERNAL:	EG&G BROWN, B	1 1	EG&G RANSOME, C	1 1
	NRC PDR	1 1	NSIC	1 1
NOTES:		1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL ~~19~~ 0

R  
I  
D  
S  
  
/

*MAY*

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

April 19, 1993

United States Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555

Serial No. 93-209  
NL/RPC  
Docket No. 50-281  
License No. DPR-37

Gentlemen:

**VIRGINIA ELECTRIC AND POWER COMPANY**  
**SURRY POWER STATION UNIT 2**  
**STEAM GENERATOR TUBE INSPECTION REPORT**

Planned inservice inspection of the Surry Unit 2 "B" steam generator was completed during the 1993 refueling outage. In accordance with Surry Power Station Technical Specifications, Section 4.19.F.a, this letter provides notification of the steam generator tubes that were plugged during the outage. In steam generator "B," two tubes (Row 40/Col 60 & Row 33/Col 63) were plugged as a precautionary measure.

If you have any questions concerning these results, please contact us.

Very truly yours,



M. L. Bowling, Manager  
Nuclear Licensing and Programs

cc: United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, N. W.  
Suite 2900  
Atlanta, Georgia 30323

Mr. M. W. Branch  
NRC Senior Resident Inspector  
Surry Power Station

000017  
9304220166 930419  
PDR ADDCK 05000281  
P PDR

A047  
1/0