PART AND ADDRESS OF THE PART A				
NRC FORM 591M PART 1 (07-2012)* 10 CFR 2 201	U.S. NUCLEAR REGULATORY COMMISSION			
SAF	ETY INSPECTION REPOR	T AND COMPLIA	NCE INSPECTION	
1. LICENSEE/LOCATION INSPECTED: Premier Energy Services, LLC 1 Dane Street Clarksburg, West Virginia REPORT NUMBER(S) 2018-001		2. NRC/REGIONAL U.S. Nuclea Region I, 21	r Regulatory Commission 100 Renaissance Blvd, Suite 100 ssia, Pennsylvania 19406-2713	
		King of Prus		
3. DOCKET NUMBER(S)		0/6/	5. DATE(S) OF IN	
030-38861	47-35262-01	4. LICENSE NUMBER(S) 47-35262-01		, 2018
LICENSEE:				
Previous violation(s) close The violation(s), specifical identified, non-repetitive, exercise discretion, were	and regulations and the conditions s. Interviews with personnel, and o indings, no violations were identificated. If you by the inspects and corrective action was or is being and corrective action was or is being the inspects and corrective action was or is being the inspects and corrective action was or is being the inspects and corrective action was or is being the inspects and corrective action was or is being the inspects and corrective action was or is being the inspects and corrective action was or is being the inspects and corrective action was or is being the inspects and inspects action.	of your license. The in bservations by the inst ed. or as non-cited violatio ing taken, and the rem	spection consisted of selector. The inspection finding in the inspection finding is a selector. The inspection finding is a selector find in the NRC English in the N	tive examinations of ngs are as follows: use they were self- nforcement Policy, to
10 CFR 30.36(d) the license have to the license to the attention of the license to the attention of the license to the license	tain of your activities, as described to NRC Enforcement Policy. This is 19.11. (Violations and Corrective Arequires in part, that licer been conducted for a per such occurrence, and be pove, as of April 3, 2018, and of many than 24 months.	form is a NOTICE OF N Actions) Insees within 60 of iod of 24 months gin decommission the licensee had	violation, which may be lays of no principal a shall provide notifice oning its site.	subject to posting in activities under ation to the
NRC in writing of	nd did not provide no sion its site.	otification to the		
	Statement of C	Corrective Action	8	
I hereby state that, within 30 days, the corrective actions is made in accordandate when full compliance will be achie	actions described by me to the ins	spector will be taken to R 2.201 (corrective ste	correct the violations identil	stens which will be taken
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE	James Clark, CFO	-/4	my flate	FO 6/6/18
	Dennis Lawyer	C	Jen 1/2	6/6/18
BRANCH CHIEF	Arthur Burritt	110	400	0/11/18
*NRC FORM 591M PART 1 (07-2012)	(RI Rev. 09/12/2013) G:	.WordDocs\Current\ins	p Record\R47-35262-01.20	18-001.591M-Part1.doc
SUNSI Review Completed By:	/RA/ Dennis Lawyer		X Public	X Non-Sensitive

NRC FORM 591M PART 2 (07-2012)		U.S. NUCLEAR REGULATORY COMMISSION				
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
LICENSEE/LOCATION INSPECTED;		2. NRC/REGIONAL OFFICE				
Premier Energy Services, LLC 1 Dane Street Clarksburg, West Virginia		Premier Energy Services, LLC 1 Dane Street Clarksburg, West Virginia				
REPORT NUMBER(S) 20	018-001					
3. DOCKET NUMBER(S)	4. LICEN	SE NUMBER(S)	5. DATE(S) OF INSPECTION			
030-38861	47-3	35262-01	April 3, June 6, 2018			

(Continued)

Specifically, the licensee has never performed principal activities since the license was issued on December 22, 2015 and the licensee had not started to work toward decommissioning as they still plan to use materials.

This is a Severity Level IV violation (Enforcement Policy Section 6.3)

The licensee commits to sending in a written notification within 30 days and has commenced decommissioning of its site.