

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

Mr. J. G.^A Keppler

FROM:

Indiana & Michigan Power Company
Bridgman, Michigan
R. W. Jurgensen

DATE OF DOCUMENT

2/18/77

DATE RECEIVED

2/25/77

☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

One signed copy

DESCRIPTION

Ltr. trans the following:

PLANT NAME:
Cook Unit No. 1

(1-P)

ENCLOSURE

Licensee Event Report (RO 50-315/77-06) on
2/4/77 concerning hydraulic shock and sway
suppressor being found to be attached to the
wrong pipe.....

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 2/28/77

RJL

<input checked="" type="checkbox"/> BRANCH CHIEF:	Ziemann
<input type="checkbox"/> W/3 CYS FOR ACTION	
<input checked="" type="checkbox"/> LIC. ASST.:	Diggs
<input type="checkbox"/> W/ CYS	
<input checked="" type="checkbox"/> ACRS 16 CYS HOLDING/SENT:	(at B. 2/28/77)

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE	
<input checked="" type="checkbox"/> NRC PDR	
<input checked="" type="checkbox"/> I & E (3)	
<input checked="" type="checkbox"/> MIPC	
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO	
<input checked="" type="checkbox"/> HOUSTON	
<input checked="" type="checkbox"/> NOVAK/CHECK	
<input checked="" type="checkbox"/> GRIMES	
<input checked="" type="checkbox"/> CASE	
<input checked="" type="checkbox"/> BUTLER	
<input checked="" type="checkbox"/> HANAUER	
<input checked="" type="checkbox"/> TEDESCO/MACCARY	
<input checked="" type="checkbox"/> EISENHUT	
<input checked="" type="checkbox"/> BAER	
<input checked="" type="checkbox"/> SHAO	
<input checked="" type="checkbox"/> VOLLMER/BUNGH	
<input checked="" type="checkbox"/> KREGER/J. COLLINS	
<input checked="" type="checkbox"/> BENEDICT	

EXTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> LPDR: St. Joseph, Mich.	
<input checked="" type="checkbox"/> TIC:	
<input checked="" type="checkbox"/> NSIC:	

CONTROL NUMBER

1935 w/o
R

28

11

11. 2. 2.

.....

(15)

(12)

100

100




INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

February 18, 1977

Regulatory Docket File

Mr. J. G. Keppler, Regional Director
United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137



Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:


Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2.a, the following report is submitted:

RO 50-315/77-06

Sincerely,

R. W. Jurgensen
Plant Manager

RWJ/mj



cc: R. S. Hunter
J. E. Dolan
G. E. Lien
R. J. Vollen BPI
R. C. Callen MPSC
K. R. Baker RO: III
R. Walsh, Esq.
P. W. Steketee, Esq.
G. Charnoff, Esq.
G. Olson
J. M. Hennigan
PNSRC
R. S. Keith
~~Dir., IE~~ (40 copies)
Dir., MIPC (4 copies)

1935

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER								LICENSE TYPE				EVENT TYPE					
01	M	I	D	C	I	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9			14	15										25	26					31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE				REPORT DATE											
01	CON'T		T	L	0	5	0	-	0	3	1	5	0	2	0	4	7	7	0	2	1	8	7	7
7	8	57	58	59	60							88	89					74	75					80

EVENT DESCRIPTION

02 While conducting surveillance, hydraulic shock and sway suppressor (Serial No. 11928) 80
7 8 9
03 was found to be attached to the wrong pipe. The snubber was attached to the 80
7 8 9
04 seal leakoff line from #2 Reactor Coolant Pump rather than the seal supply line. The 80
7 8 9
05 snubber has since been correctly installed. 80
7 8 9
06 80
7 8 9

7 8 9			SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION	
0	7		C	J	d		H	A	N	G	E	R	A	I	2	0	7	N
7	8	9	10		11		12					17	43	44			47	48

CAUSE DESCRIPTION

CAUSE DESCRIPTION			
08	7	8	9
The snubber was improperly installed during plant construction. The two pipes are			
08	7	8	9
2" dia. and are run side by side and easily mistaken.			
10	7	8	9
10	7	8	9

11	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION																																																														
H			000			NA			b			NA																																																														
FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE																																																																	
Z			Z			NA			NA																																																																	

PERSONNEL EXPOSURES

PERSONNEL EMPLOYEE									
NUMBER				TYPE	DESCRIPTION				
1	3	0	0	0	Z	NA			

PERSONNEL INJURIES

PERSONNEL NO.				NUMBER		DESCRIPTION	
7	8	9	11	12	80		
1	4	0	0	0	NA		

OFFSITE CONSEQUENCES

1	5	NA	..
7	8		80

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	NA

PUBLICITY

17	NA	80
----	----	----

ADDITIONAL FACTORS

ADDITIONAL FACTORS

18 7 8 9 80

19 7 8 9 016 465 5001 80

NAME: David G. Wizner

PHONE: 616-465-5901