

NRC DISTRIBUTION FOR T 50 DOCKET MATERIAL

FILE NUMBER

TO:
Mr. Victor Stello

FROM:
Florida Pwr. & Light Co.
Miami, Fla.
Robert E. Uhrig

DATE OF DOCUMENT
6/9/77

DATE RECEIVED
6/13/77

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
2 SIGNED

DESCRIPTION

DO NOT REMOVE

ACKNOWLEDGED

PLANT NAME:
Turkey Point Unit No. 4
RJL 6/14/77

(1-P)

ENCLOSURE

Consists of Steam Generator Inspection Report describing the results of inspections performed during the outage and contains the info. required by the Order for Modification of License dated 2/8/77.....

566
R07


(3/4")


SAFETY	FOR ACTION/INFORMATION	ENVIRONMENTAL
ASSIGNED AD:		ASSIGNED AD: V. MOORE (LTR)
BRANCH CHIEF:	<i>Leak (S)</i>	BRANCH CHIEF:
PROJECT MANAGER:	<i>Elliotte</i>	PROJECT MANAGER:
LICENSING ASSISTANT:	<i>Parkish</i>	LICENSING ASSISTANT:
		B. HARLESS

INTERNAL DISTRIBUTION			
REG FILES	SYSTEMS SAFETY	PLANT SYSTEMS	SITE SAFETY & ENVIRON ANALYSIS
NRC PDR	HEINEMAN	TEDESCO	DENTON & MILLER
T & E (2)	SCHROEDER	BENAROYA	CRUTCHEFIELD
OELD		LAINAS	
GOSSICK & STAFF	ENGINEERING	IPPOLITO	
HANAUER	KNIGHT	F. ROSA	ENVIRO TECH.
MLPC	BOSNAN		ERNST
CASE	SIWELL	OPERATING REACTORS	BALLARD
BOYD	PAWLICKI	STELLO	YOUNGBLOOD
		EISENHUT	
PROJECT MANAGEMENT	REACTOR SAFETY	SHAO	SITE TECH.
SKOVHOLT	ROSS	BAER	
P. COLLINS	NOVAK	BUTLER	GAMMILL (2)
HOUSTON	ROSZNYCZY	GRIMES	
MELTZ	CHECK		SITE ANALYSIS
HEITEMES			VOLIMER
SK	AT&T		BUNCH
	SALZMAN		J. COLLINS
	RUTBERG		KREGER

EXTERNAL DISTRIBUTION	
LPR: Miami, Fla	
TIC	NSIC
NAT LAB	
REG IV (J. HANCHETT)	
16 CYS ACRS SENT CAT	COPY B

CONTROL NUMBER
71650216





June 9, 1977
L-77-173

Office of Nuclear Reactor Regulation
Attention: Victor Stello, Director
Division of Operating Reactors
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

REGULATORY DOCKET FILE COPY



Dear Mr. Stello:

Re: Turkey Point Unit 4
Docket No. 50-251
Steam Generator Inspection Report

On May 9, 1977, the Turkey Point Unit 4, Cycle 4 refueling outage was begun. As part of the outage, the Unit 4 steam generators were inspected in accordance with the inspection program outlined in our letter of April 11, 1977 (L-77-112). The inspection program was developed in response to an NRC Order for Modification of License dated February 8, 1977.

An inspection report is attached for your review. The report describes the results of inspections performed during the outage and contains the information required by the Order for Modification of License dated February 8, 1977. Our plans for preventive tube plugging and the status of analyses in progress are also discussed. All but 66 of the tubes outlined in the inspection program have been probed. These remaining tubes will be probed before the end of the refueling outage and the same plugging criteria will be applied to them. The report concludes that continued operation of the Unit 4 steam generators is acceptable.

The NRC Order for Modification of License dated May 3, 1977 requires NRC approval before we can resume power operation. We hereby request NRC approval to return Turkey Point Unit 4 to power operation upon completion of the current refueling outage, which is scheduled to end approximately July 9, 1977.

Very truly yours,

Robert E. Uhrig
Vice President

Attachment

cc: Norman C. Moseley, Region II
Robert Lowenstein, Esquire

771650216
PEOPLE...SERVING PEOPLE

