

208/02/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)  
DISTRIBUTION FOR INCOMING MATERIAL 50-296

REC: OREILLY J P  
NRC

ORG: FOX H S  
TN VALLEY AUTH

DOCDATE: 07/25/78  
DATE RCVD: 07/28.78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED  
LTR 1 ENCL 1

SUBJECT: FORWARDING LICENSEE EVENT REPT (RO 50-296/78-019) ON 07/07/78 CONCERNING EXCESSIVE DRYWELL FLOOR DRAIN LEAK RATE OBSERVED, CAUSED BY PARTIALLY BROKEN WELD ON 1-INCH SOCKET WELD FITTING ON INSTRUMENT SENSING LINE ON A JET PUMP RISER.

PLANT NAME: BROWNS FERRY - UNIT 3

REVIEWER INITIAL: XJM  
DISTRIBUTOR INITIAL: DL

\*\*\*\*\* DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS \*\*\*\*\*

INCIDENT REPORTS  
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#3 BC\*\*W/4 ENCL

INTERNAL:

REG FILE\*\*W/ENCL  
I & E\*\*W/2 ENCL  
I & C SYSTEMS BR\*\*W/ENCL  
NOVAK/CHECK\*\*W/ENCL  
AD FOR ENG\*\*W/ENCL  
HANAUER\*\*W/ENCL  
AD FOR SYS & PROJ\*\*W/ENCL  
ENGINEERING BR\*\*W/ENCL  
KREGER/J. COLLINS\*\*W/ENCL  
K SEYFRIT/IE\*\*W/ENCL

NRC PDR\*\*W/ENCL  
MIPC\*\*W/3 ENCL  
EMERGENCY PLAN BR\*\*W/ENCL  
EEB\*\*W/ENCL  
PLANT SYSTEMS BR\*\*W/ENCL  
AD FOR PLANT SYSTEMS\*\*W/ENCL  
REACTOR SAFETY BR\*\*W/ENCL  
VOLLMER/BUNCH\*\*W/ENCL  
POWER SYS BR\*\*W/ENCL

EXTERNAL:

LPDR'S  
ATHENS, AL\*\*W/ENCL  
TIC, LIZ CARTER\*\*W/ENCL  
NSIC\*\*W/ENCL  
ACRS CAT B\*\*W/16 ENCL


A104

DISTRIBUTION: LTR 45 ENCL 45  
SIZE: 1P+1P

CONTROL NBR: 782140087

\*\*\*\*\* THE END \*\*\*\*\*

CP



**TENNESSEE VALLEY AUTHORITY**

CHATTANOOGA, TENNESSEE 37401

July 25, 1978

REGULATORY DOCKET FILE COPY

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

REGISTRATION  
SERVICES  
BRANCH

276 JUL 26 11 11

REGISTRATION  
SERVICES  
BRANCH

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET  
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE  
REPORT BFR0-50-296/7819

The enclosed report provides details concerning an excessive drywell floor drain leak rate which was observed by the operator during normal operation. This report is submitted in accordance with Browns Ferry unit 3 technical specification 6.7.2.a.(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox  
Director of Power Production

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

782140087

A002  
5/11



100  
 101  
 102  
 103  
 104  
 105  
 106  
 107  
 108  
 109  
 110  
 111  
 112  
 113  
 114  
 115  
 116  
 117  
 118  
 119  
 120  
 121  
 122  
 123  
 124  
 125  
 126  
 127  
 128  
 129  
 130  
 131  
 132  
 133  
 134  
 135  
 136  
 137  
 138  
 139  
 140  
 141  
 142  
 143  
 144  
 145  
 146  
 147  
 148  
 149  
 150  
 151  
 152  
 153  
 154  
 155  
 156  
 157  
 158  
 159  
 160  
 161  
 162  
 163  
 164  
 165  
 166  
 167  
 168  
 169  
 170  
 171  
 172  
 173  
 174  
 175  
 176  
 177  
 178  
 179  
 180  
 181  
 182  
 183  
 184  
 185  
 186  
 187  
 188  
 189  
 190  
 191  
 192  
 193  
 194  
 195  
 196  
 197  
 198  
 199  
 200



