



**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  Federal Cartridge Company P.O. Box 1151 Richmond, IN 47375  REPORT NUMBER(S) 2018001	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S)  030-11312	4. LICENSE NUMBER(S)  13-16598-01	5. DATE(S) OF INSPECTION  November 1, 2018
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED  87124	7. INSPECTION FOCUS AREAS  03.01-03.08
--	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)  03120	2. PRIORITY  5	3. LICENSEE CONTACT  Gerad Harris, RSO	4. TELEPHONE NUMBER  (765) 966-7745
---------------------------------	----------------------	--	---

Main Office Inspection                      Next Inspection Date: November 1, 2023

Field Office Inspection \_\_\_\_\_

Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

This was an unannounced, routine inspection of a small manufacturing company that employs 28 individuals in Richmond, Indiana. The licensee possessed two specifically licensed KayRay/Sensall Model 7062 fixed gauges. The licensee was authorized to possess specifically licensed fixed gauges used in the production of clay targets. Currently, one individual was involved with the use and oversight of the devices. The licensee does not perform any maintenance or removal of the gauges.

**Performance Observations**

The inspector toured the plant facilities and observed the location of the cesium-137 gauges. The inspector interviewed plant workers and determined that workers understood the proper emergency lock-out/tag-out procedures. The inspector observed the postings for the gauges. All postings were legible. The inspector performed independent radiation measurements of the fixed gauges and did not identify any readings above regulatory compliance. The inspector reviewed in office the following records: inventories, annual audits, leak tests, and shutter checks.

No violations of NRC requirements were identified as a result of this inspection.