

DSB



**Consumers  
Power  
Company**

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • (517) 788-0550

February 19, 1981


Mr James G Keppler  
Office of Inspection and Enforcement  
Region III  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60127

DOCKET 50-255 - DPR-20 - PALISADES PLANT -  
LICENSEE EVENT REPORT 81-007 - INOPERABLE  
AUXILIARY FEEDWATER PUMP

On the reverse side is LER 81-007 which is reportable under Technical Specifications 6.9.2B(2).

Steven R Frost  
Palisades Licensing Engineer

CC Director, Office of Nuclear Reactor Regulation  
Director, Office of Inspection and Enforcement  
NRC Resident Inspector



A002  
S  
1/1

FEB 23 1981

LICENSEE EVENT REPORT

CONTROL BLOCK:           (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(01) M I P A L I (2) 0 0 - 0 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 1 (4) (5)

CON'T  
(01) REPORT SOURCE L (6) 0 5 0 0 0 2 5 5 (7) 0 1 2 2 8 1 (8) 0 2 1 9 8 1 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

(02) During operator rounds it was discovered that the overspeed trip device  
(03) for the turbine-driven auxiliary feedwater pump was in the tripped  
(04) condition. The overspeed trip was immediately reset, thereby restoring  
(05) the pump to operable status. Condition is believed to have existed for  
(06) approx. one hour prior to discovery. LER 81-05 reported a similar  
(07) occurrence. Event reportable per TS 3.5.2 and 6.9.2.B2.

(08)

(09) SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
H H (11) A (12) F (13) T U R B I N (14) Z (15) Z (16)

(17) LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
8 1 0 0 7 0 3 L 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
X (18) X (19) Z (20) Z (21) 0 1 0 0 0 N (23) N (24) A (25) W 3 1 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

(10) Approx. one hour prior to discovery of the condition, contractor workers  
(11) had been observed moving gas bottles into the aux. FW pump room.  
(12) A worker apparently accidentally bumped the overspeed trip. To prevent  
(13) recurrence, indoctrination training for contractor workers is being revised  
(14) to stress necessity to exercise caution when working in vital areas.

(15) FACILITY STATUS & POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)  
E (28) 0 9 9 (29) NA A (31) Operator Observation

(16) ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)  
Z (33) Z (34) NA NA

(17) PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  
0 0 0 (37) Z (38) NA

(18) PERSONNEL INJURIES NUMBER DESCRIPTION (41)  
0 0 0 (40) NA

(19) LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)  
Z (42) NA

(20) PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY  
N (44) NA