NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION									
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSEEA.OCATION INSPECTED Ford Motor Company Research & Innovation Center 2101 Village Road MD 1049 Dearborn, MI 48121			2 NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
REPORT NUMBER(REPORT NUMBER(S) 2018001								
3. DOCKET NUMBER(S) 03()-38693		4. LICENSE NUMBER(S) 21-35113-01		5. DATE(S) OF INSPECTION					
Regulatory Commiss procedures and repr	an examination of the activities conduct ion (NRC) rules and regulations and th esentative records, interviews with pers in the inspection findings, no violations v	e conditions of you connel, and observation	r license. The inspection consis	sted of selective examination	ns of				
 Previous violation(s) closed. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied. 									
	Non-cited violation(s) were discuss	sed involving the fo	llowing requirement(s):						
During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)									
			•						
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.									
TITLE	PRINTED NAME	nat no ruither willte	SIGNATURE		DATE				
LICENSEE'S REPRESENTATIVE			_						
NRC INSPECTOR	Luis Nieves Fotch		MA		1/1-1/1				
BRANCH CHIEF	Aaron T. McCraw		Aru_	for ATM	1/29/10				
RC FORM 591M PART	1 (07-2012)								

1. LICENSERIOGATION INSPECTED: 2 INCREGIONAL OFFICE Ford Motor Company Research & Innovation Center Region III 2101. Village Road U.S. Nuclear Regulatory Commission 243 Warrenville Road, Suite 210 Liske, IL 60532-4352 REPORT NUMBER(S) 2018001 \$ DECKET NUMBER(S) 3. DOCKET NUMBER(S) \$ DATE(S) OF INSPECTION 3. GOCKET NUMBER(S) \$ DATE(S) OF INSPECTION 3. OBCKET NUMBER(S) \$ DATE(S) OF INSPECTION 3. DATE(S) OF INSPECTION INFORMATION 1 TELEPHONE NUMBER 0. TENDO	NRC FORM 591M PART 3 (07-2012) 10 CFR 2.201 SA	FETY INSPEC	Docket File Inf		U.S. NUCLEAR REGULATORY COMMISSION
2101 Village Road Region III MD 1049 Supplementation of the second state of the second stat	1. LICENSEE/LOCATION INSP	ECTED:		2. NRC/REG	SIONAL OFFICE
3. DOCKET NUMBER(S) 4. LICENSE NUMBER(S) 5. DATE(S) OF INSPECTION 030-38693 21-35113-01 January 14, 2019 6. INSPECTION PROCEDURES USED 7. INSPECTION FOCUS AREAS 87126 03.01-03.08 SUPPLEMENTAL INSPECTION INFORMATION 1. PROGRAM CODE(S) 2. PRIORITY 3. LICENSEE CONTACT 4. TELEPHONE NUMBER 03620 5 Scott Larkins, RSO (313) 323-1533 Main Office Inspection Next Inspection Date: January 14, 2024	2101 Village Road MD 1049	vation Center	U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210		
030-38693 21-35113-01 January 14, 2019 6. INSPECTION PROCEDURES USED 7. INSPECTION FOCUS AREAS 87126 03.01-03.08 SUPPLEMENTAL INSPECTION INFORMATION 1. PROGRAM CODE(s) 2. PRIORITY 3. LICENSEE CONTACT 4. TELEPHONE NUMBER 03620 5 Scott Larkins, RSO (313) 323-1533 Image: Properties of the second s		18001			
87126 SUPPLEMENTAL INSPECTION INFORMATION 1. PROGRAM CODE(S) 2 PRIORITY 3. LICENSEE CONTACT 4. TELEPHONE NUMBER 03620 5 Scott Larkins, RSO (313) 323-1533 Image: Program Code(S) 5 Next Inspection Date: January 14, 2024 Image: Program Scott Field Office Inspection Next Inspection Date: January 14, 2024 Image: Program Scott PROGRAM SCOPE PROGRAM SCOPE This was an unannounced, routine inspection of a Research and Innovation Center that was authorized by its NRC license to use radioactive isotopes of cobalt, beryllium, chromium, zinc, and manganese for the purposes of automotive research and development. At the time of the inspection, the licensee possessed only cobalt-56 in a cylinder sleeve inside of an engine block that had undergone thin-layer activation. The licensee received these components from a cyclotron operator in Germany for use in closed-loop lubricant research, conducted by one of two authorized users. Performance Observations At the time of this inspection, the inspector visited the only lab used for research to evaluate the licensee's measures for material security, hazard communication and exposure control. During this tour the RSO and one authorized user demonstrated implementation of procedures for package receipt, low-level waste handling, contamination control, and spill response. Through these demonstrations and other discussions, the inspector found that both individuals were knowledgeable of radiation protection principles. The inspector				(S)	
1. PROGRAM CODE(S) 2. PRIORITY 3. LICENSEE CONTACT 4. TELEPHONE NUMBER 03620 5 Scott Larkins, RSO (313) 323-1533 Image: Main Office Inspection Next Inspection Date: January 14, 2024 Image: Field Office Inspection Image: PROGRAM SCOPE Temporary Job Site Inspection PROGRAM SCOPE This was an unannounced, routine inspection of a Research and Innovation Center that was authorized by its NRC license to use radioactive isotopes of cobalt, beryllium, chromium, zinc, and manganese for the purposes of automotive research and development. At the time of the inspection, the licensee possessed only cobalt-56 in a cylinder sleeve inside of an engine block that had undergone thin-layer activation. The licensee received these components from a cyclotron operator in Germany for use in closed-loop lubricant research, conducted by one of two authorized users. Performance Observations At the time of this inspection, the inspector visited the only lab used for research to evaluate the licensee's measures for material security, hazard communication and exposure control. During this tour the RSO and one authorized user demonstrated implementation of procedures for package receipt, low-level waste handling, contamination control, and spill response. Through these demonstrations and other discussions, the inspector found that both individuals were knowledgeable of radiation protection principles. The inspector reviewed the annual audits, surveys, dosimetry, inventory, and shipping documents of dispose material. During the last inspection, one violation was identified for failure to perform routine				JS AREAS	
03620 5 Scott Larkins, RSO (313) 323-1533 Image: Main Office Inspection Image: Main Office Inspection Image: Main Office Inspection Image: Field Office Inspection Image: Main Office Inspection Image: Main Office Inspection Image: Temporary Job Site Inspection Image: Main Office Inspection Image: Main Office Inspection Image: Temporary Job Site Inspection Image: Main Office Inspection Image: Main Office Inspection Image: Temporary Job Site Inspection Image: Main Office Inspection Image: Main Office Inspection Image: Temporary Job Site Inspection Image: Main Office Inspection Image: Main Office Inspection Image: Temporary Job Site Inspection Image: Main Office Inspection Image: Main Office Inspection Image: Temporary Job Site Inspection Image: Main Office Inspection Image: Main Office Inspection Image: Temporary Job Site Inspection Image: Main Office Inspection Image: Main Office Inspection Inside of an engine block that had undergone thin-layer activation. The Icensee received these components from a cyclotron operator in Germany for use in closed-loop lubricant research, conducted by one of two authorized users. Performance Observations At the time of this inspection, the inspector visited the only lab used for research to evaluate the licensee's measures for material security, hazard commu		SUP	PLEMENTAL INSPECT		DRMATION
Field Office Inspection Temporary Job Site Inspection PROGRAM SCOPE This was an unannounced, routine inspection of a Research and Innovation Center that was authorized by its NRC license to use radioactive isotopes of cobalt, beryllium, chromium, zinc, and manganese for the purposes of automotive research and development. At the time of the inspection, the licensee possessed only cobalt-56 in a cylinder sleeve inside of an engine block that had undergone thin-layer activation. The licensee received these components from a cyclotron operator in Germany for use in closed-loop lubricant research, conducted by one of two authorized users. Performance Observations At the time of this inspection, the inspector visited the only lab used for research to evaluate the licensee's measures for material security, hazard communication and exposure control. During this tour the RSO and one authorized user demonstrated implementation of procedures for package receipt, low-level waste handling, contamination control, and spill response. Through these demonstrations and other discussions, the inspector found that both individuals were knowledgeable of radiation protection principles. The inspector reviewed the annual audits, surveys, dosimetry, inventory, and shipping documents of dispose material. During the last inspection, one violation was identified for failure to perform routine surveys for contamination in tho locations where individuals worked with unsealed forms of radioactive material. The inspector reviewed the corrective actions by discussing the previous violation and reviewing their survey records. The violations is closed.					
This was an unannounced, routine inspection of a Research and Innovation Center that was authorized by its NRC license to use radioactive isotopes of cobalt, beryllium, chromium, zinc, and manganese for the purposes of automotive research and development. At the time of the inspection, the licensee possessed only cobalt-56 in a cylinder sleeve inside of an engine block that had undergone thin-layer activation. The licensee received these components from a cyclotron operator in Germany for use in closed-loop lubricant research, conducted by one of two authorized users. Performance Observations At the time of this inspection, the inspector visited the only lab used for research to evaluate the licensee's measures for material security, hazard communication and exposure control. During this tour the RSO and one authorized user demonstrated implementation of procedures for package receipt, low-level waste handling, contamination control, and spill response. Through these demonstrations and other discussions, the inspector found that both individuals were knowledgeable of radiation protection principles. The inspector reviewed the annual audits, surveys, dosimetry, inventory, and shipping documents of dispose material. During the last inspection, one violation was identified for failure to perform routine surveys for contamination in tho locations where individuals worked with unsealed forms of radioactive material. The inspector reviewed the corrective actions by discussing the previous violation and reviewing their survey records. The violations is closed.	Temporary Job	Site Inspection		COPE	
At the time of this inspection, the inspector visited the only lab used for research to evaluate the licensee's measures for material security, hazard communication and exposure control. During this tour the RSO and one authorized user demonstrated implementation of procedures for package receipt, low-level waste handling, contamination control, and spill response. Through these demonstrations and other discussions, the inspector found that both individuals were knowledgeable of radiation protection principles. The inspector reviewed the annual audits, surveys, dosimetry, inventory, and shipping documents of dispose material. During the last inspection, one violation was identified for failure to perform routine surveys for contamination in tho locations where individuals worked with unsealed forms of radioactive material. The inspector reviewed the corrective actions by discussing the previous violation and reviewing their survey records. The violations is closed.	license to use radioac research and develop inside of an engine bl	tive isotopes of coment. At the time ock that had under	ection of a Research and obalt, beryllium, chromi of the inspection, the lic orgone thin-layer activation	I Innovatio um, zinc, a ensee poss on. The lic	and manganese for the purposes of automotive sessed only cobalt-56 in a cylinder sleeve censee received these components from a
for material security, hazard communication and exposure control. During this tour the RSO and one authorized user demonstrated implementation of procedures for package receipt, low-level waste handling, contamination control, and spill response. Through these demonstrations and other discussions, the inspector found that both individuals were knowledgeable of radiation protection principles. The inspector reviewed the annual audits, surveys, dosimetry, inventory, and shipping documents of dispose material. During the last inspection, one violation was identified for failure to perform routine surveys for contamination in tho locations where individuals worked with unsealed forms of radioactive material. The inspector reviewed the corrective actions by discussing the previous violation and reviewing their survey records. The violations is closed.	Performance Observa	tions			
locations where individuals worked with unsealed forms of radioactive material. The inspector reviewed the correctivactions by discussing the previous violation and reviewing their survey records. The violations is closed.	for material security, demonstrated implem spill response. Throug were knowledgeable	hazard communic entation of proce gh these demonstr of radiation prote	cation and exposure cont dures for package receip rations and other discuss ction principles. The ins	rol. During t, low-leve ions, the ir	g this tour the RSO and one authorized user el waste handling, contamination control, and nspector found that both individuals
No violations of NRC requirements were identified as a result of this inspection.	locations where indiv	iduals worked wi	th unsealed forms of rad	ioactive m	aterial. The inspector reviewed the corrective
	No violations of NRC	requirements we	ere identified as a result	of this insp	pection.