





Mr. Boyce H. Grier Director of USNRC Office of Inspections and Enforcements Region 1 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

LICENSE NO. DPR-70 DOCKET NO. 50-272 REPORTABLE OCCURRENCE 78-15/04L

Pursuant to the requirements of Salem Generating Station Unit No. 1 Environmental Technical Specifications, we are submitting Licensee Event Report for Reportable Occurrence 78-15/04L. This report is required within thirty (30) days of the occurrence.

Sincerely yours,

Alinan

F. P. Librizzi General Manager -Electric Production

CC: Director, Office of Inspection and Enforcement (30 copies) Director, Office of Management Information and Program Control

781030053



The Energy People

Report Number: Report Date: Occurrence Date: Facility:

3/9/78 Salem Generating Station Public Service Electric & Gas Company Hancock's Bridge, New Jersey 08038

# IDENTIFICATION OF OCCURRENCE:

Missed Surveillance: Non-Radwaste Sampling for Suspended Solids Analysis

7<u>2-15/04L</u>

4/6/78

### CONDITIONS PRIOR TO OCCURRENCE:

## N/A

## DESCRIPTION OF OCCURRENCE:

On the occasions summarized below, treated effluent was released from the non-radioactive liquid waste treatment basin, but a sample was not collected for suspended solids analysis.

January 1, 2, 7, 10, 14, 15, 16, 21, 24, 25, 26, 27, 28, 29, 30 February 7, 21

(Ref.: Section 2.2.2 of Appendix "B" to Operating License DPR-70) The missing samples were identified upon records review in light of Occurrence 78-10/04L.

#### DESIGNATION OF APPARENT CAUSE OF OCCURRENCE:

The cause of this occurrence was personnel error. Corrective action as stated in LER 78-10/04L had not yet been implemented.

#### ANALYSIS OF OCCURRENCE:

N/A

#### CORRECTIVE ACTION:

Responsibility to collect samples was re-assigned from demineralizer plant operator (day shift) to midnight shift Health Physics Technician.

FAILURE DATA:

N/A

Prepared by <u>T. L. Spencer</u>

SORC Meeting No. 14-78

delles sten Salem Generating Station