

REGULATORY DOCKET FILE COPY

VIRGINIA ELECTRIC AND POWER COMPANY

RICHMOND, VIRGINIA 23261

February 10, 1978

RECEIVED  
FEB 14 1978  
U.S. NUCLEAR REGULATORY  
COMMISSION  
Mail Section

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
230 Peachtree Street, Northwest  
Atlanta, Georgia 30303

Serial No. 064A/013078  
FO&M/DLB:das  
Docket Nos. 50-280  
50-281  
50-338  
License Nos. DPR-32  
DPR-37  
NPF-4

Dear Mr. O'Reilly:

This is in response to IE Bulletin 78-02 regarding terminal block qualification. This area of concern was brought to our attention on January 27, 1978 by Mr. M. B. Fairtile of the Division of Operating Reactors. As we discussed with Mr. Fairtile on January 28, 1978, Surry Unit Nos. 1 and 2 and North Anna Unit No. 1 do not use any unprotected terminal blocks in the containment in safety circuits which must operate during or subsequent to a LOCA. All such connections are enclosed in protective boxes.

Very truly yours,

*C. M. Stallings*

C. M. Stallings  
Vice President - Power Supply  
and Production Operations

cc: Mr. Edson G. Case, Acting Director ✓  
of Nuclear Regulation

Mr. Harold D. Thornburg, Director of Reactor  
Operations Inspection

*Asst*  
780460241