


Regulatory

File Cy.

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

February 16, 1977



Mr. Norman G. Moseley, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region II - Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Serial No. 062
POFM/TAP:dgt

Docket No. 50-280
License No. DPR-32

Dear Mr. Moseley:

Pursuant to Surry Power Station Technical Specification 6.6.2, the Virginia Electric and Power Company hereby submits a copy of Reportable Occurrence No. RO-SI-77-04.

The substance of this report has been reviewed by the Station Nuclear Safety and Operating Committee and will be placed on the agenda for the next meeting of the System Nuclear Safety and Operating Committee.

Very truly yours,


C. M. Stallings

C. M. Stallings
Vice President-Power Supply
and Production Operations

Enclosure

40 copies RO-SI-77-04

cc: Mr. Robert W. Reid, Chief ✓
Operating Reactors Branch 4



1774

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01 V A S P S 1 7 8 9	0 0 - 0 0 0 0 0 - 0 0 14 15	4 1 1 1 0 26	0 3 30 31 32

CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01 CON'T 7 8	M I 57 58	I 60	0 5 0 - 0 2 8 0 61 68 69	0 1 2 6 7 7 74 75	80

EVENT DESCRIPTION

- 02 During power escalation for Surry 1, cycle 4 refueling startup, the reactor exceeded
7 8 9 80
03 the 90% power hold point prior to the recalibration of the excore symmetrical off-set
7 8 9 80
04 detector system to in-core instrumentation systems as required by the Technical
7 8 9 80
05 Specification 3.18B. This was an administrative error since personnel went to the P.
7 8 9 80
06 threshold hold point at 92% power and omitted the 90% Nuclear Instrumentation(NI) (Cont'd)
7 8 9 80

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07 Z Z 7 8 9 10	A 11	Z Z Z Z Z Z 12	Z 43	Z 9 9 9 44 47	V 48

CAUSE DESCRIPTION

- 08 The unit was holding power below 90% until the NI Calibration was completed and the
7 8 9 80
09 value of P-Threshold had been determined. Upon notification of the 92% value for
7 8 9 80
10 P-threshold, the unit was erroneously ramped to that power level. Upon (Cont'd)
7 8 9 80

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11 B 7 8 9	0 9 2 10 12	NA 13	A 44 45	NA 46

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12 Z 7 8 9	Z 10	NA 11	44 45

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
13 0 0 0 7 8 9 11	Z 12	NA 13

PERSONNEL INJURIES

NUMBER	DESCRIPTION
14 0 0 0 7 8 9 11	NA 12

OFFSITE CONSEQUENCES

15 NA 7 8 9

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
16 Z 7 8 9 10	NA

PUBLICITY

17 NA 7 8 9

ADDITIONAL FACTORS

- 18 The health and safety of the general public were not affected by this occurrence
7 8 9 80

19 7 8 9

NAME: T. L. Baucom

PHONE: (804) 357-3184

GPO 881-667

EVENT DESCRIPTION (CONTINUED)

calibration hold point. The plant was at 92% power for approximately one hour before the error was noticed and an immediate reduction of power to 90% was implemented. This condition is reportable per Technical Specification 6.6.2b(3) (RO-S1-77-04).

CAUSE DESCRIPTION (CONTINUED)

realization that NI Calibration was not completed, the unit's power level was reduced to 90%. All personnel involved with the occurrence have been appropriately counseled relative to this occurrence, which should preclude recurrence.