	HOW HOWE			Abatment Industries Group	etries Group		
	ONO NOW HOVE	Activity Hozord Analysis	בו בי		,		
		Ovarall	Dial Assessma	Overall Risk Assessment Code (RAC) (Use highest code)) (Use highe	st code)	-(*
Activity/Work Task: Aspessos Abatement	Datement	\\		1			
Project Location: 71 Shelton Ave, New Haven CT 06511	, New Haven CT 06511		Risk Asse	Risk Assessment Code (RAC) Matrix	KAC) Mau	×	
Contract Number: 10-1007.00-AIG	IG	2		Pr	Probability		
Date Prepared: 10/4/2016		Severity	Frequent	Likely 0	Occasional Se)m Un	kely
	Ton Chan Estimator)	Catastrophic		E	H		_ ≤
Prepared by (Name/Title): AIG (Ian Shea, Estimator)	(lan Shea, Estimator)	Critical		H	H	M	5
Reviewed by: Sean Liddy, CSP		Marginal Negligible	M	W.	M		
Competent Person (if applicable):):	Step 1: Review each "Hazard" and determine RAC (See above)	ach "Hazard" with ic	Step 1: Review each "Hazard" with identified safety "Controls" and determine RAC (See above)			
Notes: (Field Notes, Review Comments, etc.)	ments, etc.)		the likelihood to caustified as: Frequent, Li	"Probability" is the likelihood to cause an incident, near miss, or accident and identified as: Frequent, Likely, Occasional, Seldom		KAC CHAIT	
The following outlines minimum requ	The following outlines minimum requirements per accordance with the approved AFF for the following outlines minimum requirements per accordance with the contractors are remonsible for performing tasks in accordance with the	,	,		-	make Wich Dick	
minimum requirements established fo	minimum requirements established for the site and in accordance with their own HS&E		"Severity" is the outcome uegier if an incorn, was mass accident did occur and identified as: Catastrophic, Critical, Marches 1 of Northead as	Severity. Is the outcomercegree if an incorporate reason accident did occur and identified as: Catastrophic, Critical,		H = High Risk	
company specific HS&E guidance. M	company specific HS&E guidance. Modifications or changes to the AHA should be	· †384	C(P	Step 2: Identify the RAC (Probability/Severity) as E, H, M, or L for each "Hazard" on AHA Annotate the overall highest RAC at		M = Moderate Risk	
TOT MATERIAL CONTRACTOR							
Personal Protective Equipment (PPE): ☐ Hard Hat ☐ Safety Glasses ☐ Leather Glove ☐ Safety Goggles	es 🔲 Ear Muffs 🛭 🖂	Long Pants/Sleeves	Inner Glove [Outer Glove [☐ Fall Protection☐ Cooling Vest☐	☐ Wide Brim Hat ☐ Half/Full Face	☐ Wide Brim Hat ☐ HalfFull Face Respirator	
☐ Kevlar Glove ☐ Safety Toe Boots Other PPE: Level C PPE. APR with P100 ca	Traffic Vest	Flame Resistant Clothing	Face Shield	_ Welding rfr	Can and	Canada mar tipo.	
Safety Equipment: ☐ First Aid Kit ☐ Tabling Poles	∑ Eyewash Bottles ☐ Insect Repellent	∑ Fire Extinguisher (A-B-C) Wheel Chocks	☐ Pop-up Shade		st Safe	⊠ Drinking Water ty First	
Equipment:		LA ALMAN AND AND AND AND AND AND AND AND AND A					
Monitoring Procedures and Action La ☐ PID (10.6eV) ☐ PID (11.7eV)	Monitoring Procedures and Action Levels (Refer to Section 7.0 of HASP): PID (10.6eV) PID (11.7eV) Multi-Rae (PID+O2, H2S, CO, LEL)	L) PDR (Respirable Dust)] PDM (Total Dust) ☐ Ra	☐ Radiological Meter	🛚 Personal Air Pun	ir Pun
Chemicals of Concern (COC): Asbestos	tos)				
Job Steps	Hazards		Cor	Controls		-	KAC
Identify and Secure Work	Cities the part in part of the	-Install work area boundaries, using caution tape. -Inform other trades/workers in the area as to the conditions and hazards associated	ries, using cautioners in the area as	n tape. to the conditions	and hazards ass	ociated	Ē
Areas		with the work to be performed. - Identify possible slip, trip, and fall hazards such as holes, obstructions protruding from the ground, or debris that may be scattered on the ground. Contact site manager immediately and do not proceed if any conditions are observed that could make	rmed. ip, and fall hazard s that may be scat roceed if any con	is such as holes, o tered on the grounditions are observ	bstructions prot nd. Contact site ed that could m	ruding manager ake	
		sampling location area unsafe. -Watch where you step and do not place prior to starting work.	safe. nd do not back/sterk.	back/step into any open holes. Ensure covers in	oles. Ensure co	vers in	

- Use proper ergonomic lifting technique. Get help in lifting heavy or awkward objects. Establish and maintain clear work area/path. Make sure equipment is in good	Sprains/Strains from lifting	
- Maintain housekeeping around work areaKeep work area clear of surface encumbrances	Tripping hazards from power extension cords	
 -Use leather gloves and avoid sharp metal and protruding objects. -Check integrity of all equipment power supply cords. Use GFCI on outlets. - Use proper tools and follow manufacturer's instructions. 	Potential for cuts from hand tools Shock from electrical supply	
Personal performing abatement will be equipped with, protective suits, ½ face or PAPR respirators, hard hats, safety glasses and work boots.	fibers.	out
-Method of removal will be wet methods under full containment with negative	Potential for exposure to asbestos	Bagging up waste and loading
Avoid areas in which potential fall hazards (≥ 6 ft to lower level) are present. Use fall protection if exposed to fall ≥ 6 ft to lower level.		
Fully extend and lock spreaders on step ladders. Maintain 3 points of contact when ascending and descending. Keep hands free of additional material when climbing. Use a rope to lift material and tools. Do not overextend when working by reaching out to far on the side of a ladder. Keep your belt buckle between the two side rails.		
Ensure proper type of ladder selected for application. Before use, check the load rating of the ladder, to make sure the ladder can support the combined weight of the user, the weight of tools, and the weight of any material that will be placed on the ladder. This includes the weight of anything that may be supported by the user.	Falls from ladders	Use of Portable Ladders and fixed ladders
- Use proper ergonomic lifting technique. Get help in lifting heavy or awkward objects. Establish and maintain clear work area/path. Make sure equipment is in good condition.	Sprains/Strains from lifting	
- Maintain housekeeping around work areaKeep work area clear of surface encumbrances	Tripping hazards from power extension cords	
employees. -Use leather gloves and avoid sharp metal and protruding objects. -Check integrity of all equipment power supply cords. Use GFCI on outlets. - Use proper tools and follow manufacturer's instructions.	Potential for cuts from hand tools Shock from electrical supply	
-Prior to start of work, all ladders will be inspected and certified as sale for use. -Proper training for ladder and hand tools will be performed with all applicable	Potential for falls from ladders	Containment Setup
Controls	Hazards	Job Steps

Job Steps	Hazards	Controls
Asbestos Abatement &	Potential for exposure to asbestos	-Method of removal will be wet methods under full containment with negative
clearance sampling	fibers.	pressure. -Personal performing abatement will be equipped with, protective suits, ½ face or PAPR respirators, hard hats, safety glasses and work boots.
	Potential for cuts from hand tools Shock from electrical supply	 -Use leather gloves and avoid sharp metal and protruding objects. -Check integrity of all equipment power supply cords. Use GFCI on outlets. - Use proper tools and follow manufacturer's instructions.
	Tripping hazards from power extension cords	 Maintain housekeeping around work area. Keep work area clear of surface encumbrances
	Sprains/Strains from lifting	- Use proper ergonomic lifting technique. Get help in lifting heavy or awkward objects. Establish and maintain clear work area/path. Make sure equipment is in good condition.
	Chemical exposure from mastic remover	-Containment well ventilated to reduce exposure potential -Wear appropriate PPE and review Safety Data Sheet for product prior to use.
Containment Breakdown	Potential for falls from ladders	-Prior to start of work, all ladders will be inspected and certified as safe for useProper training for ladder and hand tools will be performed with all applicable employees.
	Potential for cuts from hand tools Shock from electrical supply	 -Use leather gloves and avoid sharp metal and protruding objects. -Check integrity of all equipment power supply cords. Use GFCI on outlets. - Use proper tools and follow manufacturer's instructions.
	Tripping hazards from power extension cords	- Maintain housekeeping around work areaKeep work area clear of surface encumbrances
	Sprains/Strains from lifting	- Use proper ergonomic lifting technique. Get help in lifting heavy or awkward objects. Establish and maintain clear work area/path. Make sure equipment is in good condition.

Additional Safety Considerations

- Submit SDS to SSHO for all chemical brought on-site and review with work crew prior to use
- Sin unnecessary confusion. Watch for overhead utilities. Wear high visibility vest or shirt at all times. Use caution around delivery trucks and stay clear if not involved in spotting operation. Use one person to communicate with driver via hand signals to avoid
- 4. in the cab or bed or the truck. It can cause property damage or serious injuries to others or yourself by falling-off from vehicle. Stow all materials in vehicle properly, use appropriate cases and bags. Secure equipment in bed of truck with netting or straps. Do not leave any equipment loose
- S correct. Use a buddy to help secure equipment when possible. When securing equipment, watch for pinch points. Straps and netting can get caught on objects and snap back as well as trap a finger if hand placement is not
- 9 Keep clear area around work area, maintain good housekeeping practices. When possible, use mechanical equipment to perform lifting of heavy objects. When lifting, follow safe lifting practices. Use the buddy system when lifting.
- 7 Keep line of site with co-worker and ensure regular verbal contact. If out of the line of site, ensure radio or cell phone contact is established and maintained.

Contact Name	Cabrera Contacts	Number	Contact Information AIG Project Contacts Contact Name	Number
Contact Name	Title		Contact Name	Number
Gree Bright	ager	C: 781-264-4445 O: 508-315-6246 Fran Mooney	Fran Mooney	203-410-3137
Sean Liddy	l	C:443-553-1403 O:667-207-2942	Ian Shea	203-410-8930
			Chris Powers	203-410-8926
			Jayson Williston	203-687-3833

Equipment to be Used	Inspection Requirements	Training Requirements
Utility Vehicles	Daily Preventative Maintenance Checks	Vehicle & Driver Safety Awareness Familiarity with the vehicle being operated.
Communications Equipment	Daily communications Checks	Familiarity with the equipment. Knowledge of Emergency Response Procedures.
Hand Tools, Sprayers, step ladders, utility Inspect hand tools and ladders daily knives scrapers	Inspect hand tools and ladders daily	Use hand tools for their intended purposes. Familiarity with the equipment.
Ladders	Daily inspection of ladders before use.	Use type of ladder (step/extension) for their intended purposes. Familiarity with the equipment.
		Other Training: -Evacuation, Emergency Response & Notification Procedures IAW APPSafe work practices and precautions IAW APPOSHA qualifications and training as required IAW APP.

By signing this form, AIG employees agree that: All employees, subcontractors, and visitors must sign the Acknowledgement form, in this section, before conducting field activities at this site.

- I have read this Activity Hazard Analysis and I understand the requirements of the AHA.
- I will conduct work at this site in accordance with the requirements of the AHA.

By signing this form, subcontractors and visitors agree that:

- I have read and understood the potential hazards associated with the site.
- I have read this Activity Hazard Analysis and I understand the requirements of the AHA.
- I will conduct work at this site in accordance with the requirements of the AHA.
- I will ensure compliance with my company's policies on health and safety.

	,		
		-	
A	MIG	21/50/2	Alexander Colle
The state of the s	AIG	2/23/17	Fred Exects
	Chreron	2/121/17	Nich Berliner
	Calvar	2/01/17	Alorary
11	Ais	4-16-16	Rory GRAM
7	BG	2-21-17	Chris Powers
	AIG	71-15-6	to Shear
0	Cabrera	2/21/17	Ann hicks
	Company	Date	Name (Print)