OP 590 - Elevated Work Platforms CABRERA SERVICES A 1994 - 1994 - 18 IEW Plint paction Forms is a second EWP Operator must inspect/document equipment daily, using this form. Project Name: 71 Shelton AVE **Project Number:** Date: 3-27-17 Make/Model: Sissor Lift Operator: R. Gray Inspection **EWP** Inspection Satisfactory Unsatisfactory N/A General appearance (hood, paint, undercarriage) 0 Tires (adequate tread) 4 Batteries (tie-downs in place, corroded, leaking) U Hydraulic Oil Levels 0 Engine Oil Levels 9 Coolant Levels Structural Arms (welds and paint condition) TU Chain properly lubricated 14 Outriggers deployed and stable 0 4 Basket in sound condition (toe boards, flooring) 0 P Guardrails intact, swing gate functional 4 Controls properly marked/labelled and functional 1 Ground controls (emergency override) functional Motion Alarm functional 9 Fire Extinguisher (min 5 lbs B:C) ar Operators manual present Utilities -Safe distance from overhead lines (min 10 feet) Work Area 9 Work zone demarcated and barriers erected D Non-essential personnel behind barriers 6 Area clear of obstructions, holes, uneven surfaces 2 Travel routes clear and demarcated Overhead obstructions marked Personal Protective Equipment Fall protection (harness and lanyard) available and in use Anchorage points intact Comments: Unit in good Condition