OP 590 - Elevated Work Platforms

1	CARREDA	SERVICES
.420000	CADILLIA	DEKAICES
Concept States	RADIOLOGICAL - ENGIR	NEERING - REMEDIATION

EWP Inspection Form							
EWP Operator must inspect/document equipment daily, using this form.							
Project Name:	Project Number:	Date: 3 - 2 2 - 1 7					
Operator:	perator: Make/Model:						
Inspection							
EWP Inspection		Satisfactory	Unsatisfactory	N/A			
General appearance (hood, paint, undercarriage	4						
Tires (adequate tread)							
Batteries (tie-downs in place, corroded, leaking)	Ð						
Hydraulic Oil Levels			8				
Engine Oil Levels							
Coolant Levels			9				
Structural Arms (welds and paint condition)	1						
Chain properly lubricated							
Outriggers deployed and stable							
Basket in sound condition (toe boards, flooring)							
Guardrails intact, swing gate functional							
Controls properly marked/labelled and functional							
Ground controls (emergency override) functional							
Motion Alarm functional							
Fire Extinguisher (min 5 lbs B:C)	2						
Operators manual present							
Utilities							
Safe distance from overhead lines (min 10 feet)	0						
Work Area							
Work zone demarcated and barriers erected							
Non-essential personnel behind barriers		Ð					
Area clear of obstructions, holes, uneven surfaces							
Travel routes clear and demarcated	e e						
Overhead obstructions marked							
Personal Protective Equipment							
Fall protection (harness and lanyard) available a							
Anchorage points intact							
Comments:							