THOMAS ELECTRIC AND FOMER CUMPANY

February 14, 1975

Unit 1

Director of Regulator Operations 230 Peachtree St. Suite 818 Atlanta, Georgia 30303

Dear Str:

This is to officially inform you by telecopy within twenty-four (24) hours of an abnormal occurrence that occurred on February 14, 1975 at Surry Nuclear Power Station.

While conducting periodic calibration tests of pressurizer pressure comparator, it was determined the comparator was out of calibration. The setpoint had drifted below the limit specified in technical specification 3.2. Reactor was at 700 MRe. The comparator was replaced.

> E.M. Sweeney, Jr. Station Manager