

NARRATIVE OF LICENSEE EVENT REPORT 78-05/99T

On October 22, 1977, a surveillance of the TMI dike revealed an area where the rock rip-rap had moved down the slope of the dike. An area approximately 30 feet in length moved approximately 15 feet down the slope. The degradation occurred immediately above Outfall 004, as described in the TMI Unit 1 and Unit 2 Environmental Report. This item is reportable in accordance with Technical Specification 4.7.6.1.3.

This event was believed to have been caused by the fact that the incline of the slope was greater than 2:1.

To prevent any recurrence of this situation, Met-Ed has replaced the rock rip-rap in position with a slope not exceeding 2:1. Periodic surveillance will be performed in accordance with the Unit Technical Specification.

12-357

79041001<sup>6</sup>85

