

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | P | A | T | M | I | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 1 | 4 | 5  
9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 56 58

01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 2 | 0 | 7 | 0 | 5 | 1 | 2 | 7 | 8 | 9 | 0 | 6 | 1 | 1 | 2 | 7 | 8 | 9  
80 DOCKET NUMBER 88 89 EVENT DATE 74 75 REPORT DATE 80

02 | While performing the monthly Reactor Building Isolation and Cooling/Safety Injection  
03 | Surveillance, the setting of BS-PS-3260 was found to be greater than its allowable  
04 | value as indicated in Technical Specification 3.3.2.1 by 0.02 psig. Since redundant  
05 | pressure switches were available and within calibration, there was no effect on the  
06 | health and safety of the public.

07 | \_\_\_\_\_  
08 | \_\_\_\_\_

09 | SYSTEM CODE | S | D | 11 | CAUSE CODE | X | 12 | CAUSE SUBCODE | Z | 13 | COMPONENT CODE | Z | Z | Z | Z | Z | Z | 14 | COMP. SUBCODE | Z | 15 | VALVE SUBCODE | Z | 16 |  
17 | LEP/RC REPORT NUMBER | 17 | 18 | 21 22 | SEQUENTIAL REPORT NO. | 0 | 3 | 8 | 26 | OCCURRENCE CODE | 0 | 3 | 28 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32 |  
ACT ON TAKEN | F | 18 | 33 | FUTURE ACTION | Z | 19 | 34 | EFFECT ON PLANT | Z | 20 | 35 | SHUTDOWN METHOD | Z | 21 | 36 | HOURS | 0 | 0 | 0 | 22 | 37 38 | ATTACHMENT SUBMITTED | N | 23 | 41 | NPRO-4 FORM SUB. | N | 24 | 42 | PRIME COMP. SUPPLIER | Z | 25 | 43 | COMPONENT MANUFACTURER | Z | 9 | 9 | 9 | 44

10 | BS-PS-3260 error was determined to have been caused by instrument drift during the  
11 | surveillance time frequency. Corrective action was taken by adjusting the pressure  
12 | switch to a value below the technical specification trip setpoint. No future action  
13 | is required since monthly surveillance will be performed as required.

14 | \_\_\_\_\_  
15 | FACILITY STATUS | 2 | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | L | 31 | DISCOVERY DESCRIPTION | Discovered during testing | 32 |

16 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36 |

17 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | 2 | 38 | DESCRIPTION | NA | 39 |

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41 |

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43 |

20 | PUBLICITY ISSUED | 1 | 44 | DESCRIPTION | Weekly News Release | 45 |

NAME OF PREPARED James R. Stair

60-278 69  
PHONE 219-929-3601, Ext. 118

7900200384