

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

REPORT SOURCE 60 015 10 10 10 131 211 70 18 10 12 17 19 80 018 117 719 80
60 61 COCKET NUMBER 63 64 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | Coil for relay A71-K25 in panel H11-P623 was found to not energize with voltage across
013 | it while performing the RWCU auto isolation LSFT. This relay indirectly closes the
014 | RWCU pump suction valve which allows running of either RWCU pump when no non-regenera-
015 | tive heat exchanger high temperature signal is present. The unit was shutdown, so
016 | RWCU was not required at the time. This is a non-repetitive occurrence.

1 **2** **3** **4** **5** **6** **7** **8** **9** **10** **11** **12** **13** **14** **15** **16** **17** **18** **19** **20** **21** **22** **23** **24** **25** **26** **27** **28** **29** **30** **31** **32** **33** **34** **35** **36** **37** **38** **39** **40** **41** **42** **43** **44** **45** **46** **47** **48** **49** **50** **51** **52** **53** **54** **55** **56** **57** **58** **59** **60** **61** **62** **63** **64** **65** **66** **67** **68** **69** **70** **71** **72** **73** **74** **75** **76** **77** **78** **79** **80** **81** **82** **83** **84** **85** **86** **87** **88** **89** **90** **91** **92** **93** **94** **95** **96** **97** **98** **99** **100**

ANSWER:

CAUSE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE
CODE SUBCODE

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE			
1 CI G (11) 9	2 E (12) 11	3 A (13) 12	4 R E I L J A Y X (14) 13	5 A (15) 19	6 Z (16) 20			
SEQUENTIAL REPORT NO.			OCCURRENCE CODE	REPORT TYPE	REVISION NO.			
(17) LEP RD REPORT NUMBER 1 [719] 2	18 EVENT YEAR 2 [] 22	19 [] 23	20 [057] 24	21 [] 27	22 [013] 28	23 [L] 30	24 [] 31	25 [0] 32
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22) 31	ATTACHMENT SUBMITTED 41	NPRO-4 FORM SUB 42	PRIME COMP. SUPPLIER 43	COMPONENT MANUFACTURER 44
1 A (18) 33	2 Z (19) 34	3 Z (20) 35	4 Z (21) 36	5 [00010] 37	6 N (22) 40	7 Y (24) 42	8 N (25) 43	9 G 10 18 10 (26) 45

Relay failed due to burned out coil. Relay has been replaced and retested.

100% of the time, the system will be able to correctly identify the target object.

10. The following table shows the number of hours worked by 100 employees of a company.

1 2

FACILITY STATUS 1 POWER OTHER STATUS 20
1 3 G 23 0 0 0 29 N/A 44
7 8 9 10 11 12 13 45 46 47
DISCOVERY DESCRIPTION 32
N/A 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTIVITY CONTENT
RELEASED OR RELEASED
AMOUNT OF ACTIVITY (35)
N/A

7 8 9 10 11 12 - 60
PERSONNEL INDUSTRIES
NUMBER 4 DESCRIPTION (4)

--	--	--

 N/A

782 087

N/A 02-007
NRC USE ONLY

NFC USE ONLY

卷之三

7908240 411