



**Commonwealth Edison**  
Zion Generating Station  
Shiloh Blvd. & Lake Michigan  
Zion, Illinois 60099  
Telephone 312/746-2084

*DLE*

August 20, 1979

Mr. James G. Keppler  
Regional Director  
Directorate of Regulatory Operations  
Region III  
U.S. Nuclear Regulatory Commission  
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station  
Docket No. 50-295/DPR-39  
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/79-56 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 8/6/79 and by telegram on 8/7/79.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a.(9) which states that performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the safety analysis report or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition requires a 14 day written report

Very truly yours,

*for C. E. Schumann*  
N. E. Wandke  
Superintendent  
Zion Station

Enclosure: Reportable Occurrence Report No. 50-295/79-56

*1002  
8/11*

943 127

**POOR ORIGINAL** JG 21 1979

7909120

*475*