



EVENT DESCRIPTION AND PROBABLE CONSEQUENCES CONTINUED

This event is not considered to have any effects upon public health or safety because of the installed low pressure trip points.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

to normal pressure. The light source was replaced in the bistable and the control system put back into its normal configuration. This type of bistable is planned to be changed out to a solid state design bistable which will be more reliable.