

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C T H N P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 - 0 2 1 3 7 0 2 1 5 7 9 8 0 9 1 1 7 9 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 Refer to original LER 79-3/3L dated 3/14/79.

0 3

0 4

0 5

0 6

0 7

0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
A B 11 E 12 A 13 E N G I N E 14 Z 15 Z 16
7 8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER EVENT YEAR 7 9 21 22
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
B 18 Z 19 Z 20 Z 21 0 0 0 0 22 Y 23 N 24 A 25 D 0 9 2 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 As described in the original LER the pump shaft was found frozen in a block of ice.

1 1 To prevent this from happening in the future a Plant Design Change has been approved

1 2 which will allow installation of 1/2" line coming off the service water header to be

1 3 run to both pump discharge columns to prevent the water in these columns from

1 4 becoming stagnant. This modification will be installed prior to cold weather.

1 5 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
H 28 0 0 0 29 NA IC 31 Operator observation
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 40 NA
7 8 9 10 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 NA
7 8 9 10 80

2 0 PUBLICITY ISSUED DESCRIPTION
N 44 NA
7 8 9 10 80

NAME OF PREPARER

James M. Levine

PHONE

(203) 267-2556

NRC USE ONLY

956305

790917045B